

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005590/KPA3Q2**Date:** 28/10/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNC5774K**Insured Vehicle No :** SME8121B

Date of Loss: 09/06/2022

Nature of Claim: TP Claim No: 2770375044SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC5774K**

Make & Model: HONDA FIT, 1.3 (A)

Engine No: L13B1522270

Reg. Date: 28/10/2021 (Man. Year: 2020)

Chassis No: GR11016994

Colour: Metallic Silver

Odometer: 18716 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,604.12	2,519.96	84.16	3.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,300.00	350.00	21.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,254.12	3,819.96	434.16	10.21
+ GST 7.00/7.00% (\$\$)	297.79	267.40	30.39	10.21
Nett Amount (\$\$)	4,551.91	4,087.36	464.55	10.21
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (\$\$)		428.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,517.36		

INSPECTION

Date of Assignment: 14/06/2022

Date Inspected: 14/06/2022 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	997.00 FL	*997.00 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Serviceable	27.00 FL	*- FL
3	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
4	1		*REAR TAILGATE	Bent	1,190.70 FL	*1,190.70 FL
5	1		*TAILGATE EMBLEM (FIT)	Necessary	32.10 FL	*32.10 FL
6	1		*TAILGATE INNER LOCK	Dented	240.10 FL	*240.10 FL
7	1		*TAILGATE INNER RUBBER	Cut	90.10 FL	*90.10 FL
8	1		*SET REAR WINDSCREEN GLASS MOULDING	Necessary	117.90 FL	*117.90 FL
9	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
10	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
11	1		*SMART KEY SENSOR	Dented	76.40 FL	*76.40 FL
12	2		*REAR BUMPER BRACKETS	Repair	78.20 FL	*- FL
13	1		*REAR TAILGATE INNER POCKET	Dented	38.50 FL	*38.50 FL
14	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
					Sub Total (\$\$)	3,186.40 3,081.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	582.28 561.24
					Total Parts (\$\$)	2,604.12 2,519.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILGATE ,REAR WIPER ,SPOILER ASSY ,LOCK ASSY ,REFLECTORS AND TAILLAMPS ,TO KNOCK & REPAIR REAR PANEL AND REALIGN THE SAME	New	700.00	500.00
3	PUTTY & RESPRAY ON REAR PANEL ,REAR BUMPER ,TAILGATE ,REAR AFFECTED AREAS	New	750.00	600.00
4	REMOVE & REFIX REVERSE CAMERA ,SENSOR ,SMART KEY SENSOR AND RESET SYSTEM	New	50.00	50.00
5	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,650.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >