

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SNC 5774K

TP/AIG

*Not Authorized
 Resurvey B4 paint*

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department \ MR YAP/MR
 WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 09/06/2022
 TP Veh Reg No: SME8121B

4 days

Estimate No: ES2290585/YISHUN
 Date: 14 Jun 2022
 Policy No: D21MTPV01015404
 Veh Reg No: SNC5774K
 Make/Model: HONDA HONDA FIT 1.3
 Chassis No: GR11016994
 Engine No: L13B1522270
 Reg. Date: 28/10/2021

Estimate Repair Cost to Vehicle No :SNC5774K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER <i>997</i>	997.00	1 PC	<i>By</i> 997.00	✓
2 REAR BUMPER LH SIDE RETAINER	27.00	1 PC	<i>By</i> 27.00	✓
3 REAR BUMPER CLIPS	3.90	6 PCS	<i>By</i> 23.40	✓
4 REAR TAILGATE <i>1190.70</i>	1,190.70	1 PC	<i>By</i> 1,190.70	✓
5 TAILGATE EMBLEM (FIT)	32.10	1 PC	<i>By</i> 32.10	✓
6 TAILGATE INNER LOCK	240.10	1 PC	<i>By</i> 240.10	✓
7 TAILGATE INNER RUBBER	90.10	1 PC	<i>By</i> 90.10	✓
8 REAR WINDSCREEN GLASS MOULDING	117.90	1 SET	<i>By</i> 117.90	✓
			2,718.30	
		Less 20%	543.66	2,174.64
Special Net				
9 REAR WINDSCREEN GLASS GUM	40.00	1 PC	<i>By</i> 40.00	✓
10 REAR NUMBER PLATE	35.00	1 PC	<i>By</i> 35.00	✓
			75.00	75.00
Labour				
11 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
12 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR WIPER, SPOILER ASSY, LOCK ASSY, REFLECTORS AND TAILLAMPS, TO KNOCK & REPAIR REAR PANEL AND REALIGN THE SAME	700.00	1 LA	700.00	<i>500</i>
13 PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER, TAILGATE, REAR AFFECTED AREAS	750.00	1 LA	750.00	<i>600</i>
14 REMOVE & REFIX REVERSE CAMERA, SENSOR, SMART KEY SENSOR AND RESET SYSTEM	50.00	1 LA	50.00	✓
15 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,650.00	1,650.00

Total SS 3,899.64

Add GST @ 7% 272.97

Total Amount Payable SS 4,172.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE