

ASS. REC. BY:

REF:

LPC / 22005606 / Ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

SMRT

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/7/21 Sat @ 1300h Car

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

ort Format :

m / I.B.I. (\$



Case Details

Case Reference Number : TAX/06/22/2040
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5081C

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-18537-ID
 Assigned By : Kwai Leng Gan

Insurance Company Name : Lonpac Insurance Bhd
 Accident Date and Time : 11/06/2022 07:00 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5	Replace	B/Dit ✓
Standard	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓
Standard	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	dit ✓
Standard	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	✓
Standard	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	✓
Standard	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	✓
Standard	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Not Give	✓
Standard	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give	✓
Standard	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give	✓
Standard	Main			BUMPER FRT ABSORBER LOWER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	✓
Total Spare Part Cost									7,990.37	Surveyor Total		600.37		
Standard	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	✓
Standard	Main			SUPPORT SUB-	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give	✓
Final Spare Part Cost									6,392.30	Final Sur Total		480.30		

ASSY SMRT Recommendation											Surveyor Approval				Remarks
Standard Type	Costing Type	Portion	Material Number	HEAD LAMP RH	Qty	245.20 Price Per	245.20 Price(\$)	00.00 (%)	245.20 Price(\$)	Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Check	Replace	
Standard	Main			SUPPORT RADIATOR, RH	1	54.50	54.50	25.00	40.88	Replace	0	0	Not Give		
Standard	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair		
Standard	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	1	38.92	Replace		Me
Standard	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Not Give		
Standard	Main			FENDER SEAL TO COWL SIDE RH	1	15.20	15.20	25.00	11.40	Replace	0	0	Not Give		
Standard	Main			FENDER LINER PAD, FR WHEEL, RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give		
Standard	Main			FENDER APRON SUB FRT/RH	1	637.80	637.80	25.00	478.35	Replace	0	0	Not Give		
Standard	Main		6505658	WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair		
Standard	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give		
Standard	Main			CAP SUB-ASSY, WHEEL	1	174.10	174.10	25.00	130.58	Replace	1	130.5	Replace		pd ✓
Standard	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Check	chk a	sn X
Standard	Main			LOWER ARM FRT/RH	1	625.90	625.90	25.00	469.42	Replace	0	0	Check	chk a	sn X
Standard	Main			SHOCK ABSORBER FRT/RH	1	394.20	394.20	25.00	295.65	Replace	0	0	Check	chk a	sn X
Standard	Main			SHOCK ABSORBER MOUNTNG FRT,RH/LH	1	193.80	193.80	25.00	145.35	Replace	0	0	Check	chk a	sn X
Standard	Main			SHOCK ABSORBER BEARING, FRT LH/RH	1	34.00	34.00	25.00	25.50	Replace	0	0	Check	chk a	sn X
Total Spare Part Cost											Surveyor Total		600.37		
Lump Sum Discount (%)											Lump Sum Dis (%)		20.00		
Final Spare Part Cost											Final Sur Total		480.30		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION FRONT	676.00	300.00	
Total:			676.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,296.00	460.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00	
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00	
4	Main	RESPRAY WHEEL CAP	180.00	0.00	
5	Main	TO RESPRAY RIM	180.00	60.00	
Total:			1,296.00	460.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20.00	
Total:			500.00	80.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,392.30	480.30
Total Labour Cost	676.00	300.00
Total Spray Painting	1,296.00	460.00
Other	500.00	80.00
Overall Total	8,864.30	1,320.30
Lump Sum Repair Option	☐	☒
Lump Sum Total	8,850.00	1,300.00
Surveyor Approved Amount		1,300.00
No of Repair Days*	5	3