



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0491/2022/JT
DATE : 13-Jun-22
WIP : 28496

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 16/6/2022.

YOUR INSURED VEH NO : SMP 8566 T

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

OWNER'S NAME : MR. LOO HUAN LIONG
ADDRESS : 431A BEDOK NORTH ROAD
#06-441
SINGAPORE 461431
TELEPHONE : HP +65 86606778
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900233479-01
VEHICLE NO : **SMQ 241 C**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 25/10/2019
ENGINE NO : CHZ C34871
CHASSIS NO : WAUZZZ8V9LA007106
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jun-22
PLACE OF ACCIDENT : 2 EUNOS CRESCENT, OPEN CARPARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 241 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 1,050.00	
4	TO RESPRAY FRONT BUMPER.	\$ 900.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 241 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,433.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 318.00	
4	FRONT BUMPER TRIM COVER - LH	1	\$ 182.00	
5	RADAIATOR GRILLE	1	\$ 1,578.00	
6	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	
7	AIR COND STICKER	1	\$ 9.00	
8	CAUTION STICKER	1	\$ 16.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 210.00	
10	HEADLIGHT - LH	1	\$ 5,879.00	
11	RADIATOR AIR GUIDE - LH	1	\$ 28.00	
12	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 14.00	
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	
14	FRONT NO PLATE	S/N	\$ 60.00	
15	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 11,693.00	
TOTAL LABOUR CHARGES		:	\$ 2,852.00	
GRAND TOTAL		:	\$ 14,545.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT