

Taught

ce4/LPC22 005609/Трaз

ASSIGNMENT

Veh No: FBL9774 Yr Regn: 2015 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW R1200 GS C.C. 1170.

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WB1047008DZ J30770

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Mil / S/Rim / STD A/Rim 9

Tyre Size: F: 110/80/49

R: 150 / 70/17.

	
N/S	O/S
	

PS / DIUN / EYNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or TimSun

Front _____ Rear _____

R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

DOA _____ D.O.I. 7/6/22 @ 4an

Survey held at MKL

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐ : Preli. Report
☐ : Final Report

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Transportation:

ii) $S \div RS, \underline{\quad} SI$

3) Photos

Others

TOTAL

[illegible]



HKL LIM
TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBL977U

1	TOP BOX	\$980 <i>del</i>
2	TOP BOX BRACKET	\$860 x
3	SIDE BOX RH	\$950 x
4	SIDE BOX BRACKET	\$1,100 x
5	REAR WHEEL RIM	\$2,300 x
6	DRIVE SHALF	\$3,800 x
7	LABOUR	\$850 <i>100</i>

TOTAL AMOUNT:

\$10,840

Taufik 97495749
WP 7/6/22 @ 11am
Taufik @ 11auto.com
Resurvey new parts
o/day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: