



Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBL977U

1	TOP BOX	\$980
2	TOP BOX BRACKET	\$860
3	SIDE BOX RH	\$950
4	SIDE BOX BRACKET	\$1,100
5	REAR WHEEL RIM	\$2,300
6	DRIVE SHALF	\$3,800
7	LABOUR	\$850

TOTAL AMOUNT: \$10,840