



HKL LIM TEAM MOTORSPORT

Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBL977U

- 1 TOP BOX
- 2 TOP BOX BRACKET
- 3 SIDE BOX RH
- 4 SIDE BOX BRACKET
- 5 REAR WHEEL RIM
- 6 DRIVE SHAFT
- 7 LABOUR
- 8 Sticker Wrap

\$980 *dd*
\$860 x
\$950 x } *x*
\$1,100x } *nn*
\$2,300 x
\$3,800 x
\$850 *100*
\$300 150

TOTAL AMOUNT:

\$10,840
980
10% 882
100
150
\$1132
** 01 day*

Taufik 97495749
WP 7/6/22 @ 11am
taufik @ 11am
Resurvey new parts
01 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: