

◆ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0468/2022/JT
DATE : 7-Jun-22
WIP : 27472

Xiao Tony.

08 Days.

\$19373.76

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 14/6/2022

YOUR INSURED VEH NO : SDP 4555 H

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

OWNER'S NAME : MR KIM SANG HYUCK
ADDRESS : 212 DEPOT RD, THE INTERLACE
#05-64
SINGAPORE 109700
TELEPHONE : HP +65 96656604
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210111411
VEHICLE NO : **SNB 9638 A**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S-TRONIC
MODEL YEAR : 23/9/2021
ENGINE NO : DKY 015537
CHASSIS NO : WAUZZZF26MN076080
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Jun-22
PLACE OF ACCIDENT : LOWER DELTA ROAD & KAMPONG BAHRU ROAD
(AT TRAFFIC LIGHT TO TURN TO MOUNT
FABER ROAD FROM LOWER DELTA ROAD)

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 9638 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N S	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N S	280.00	✓
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N S	1,600.00	✓ H.S.
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S	4,800.00	1000 2500 H.S.
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND REAR END PANELLING.	S	3,500.00	1100 2200 H.S.
6	TO RENEW REAR EXHAUST SILENCER AND ALIGN INTO POSITION	S/N S	480.00	X
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 11,212.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 9638 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	1 S	3,012.00	✓ 2,409.60
2	REAR BUMPER TELEPHONE AERIAL - LH / RH <i>2H Rhd</i>	2 S	182.00	✓ 91 72.72
3	REAR BUMPER FIXING PARTS <i>new</i>	1 S	247.00	✓
4	REAR BUMPER SPOILER <i>Delnd</i>	1 S	985.00	✓ 787.60
5	REAR BUMPER CHROME TRIM - LH <i>new</i>	1 S	273.00	✓ 154.80
6	REAR BUMPER CHROME TRIM - CENTER <i>new</i>	1 S	194.00	✓ 154.00
7	REAR BUMPER SECURING STRIP <i>Distd</i>	1 S	193.00	✓
8	BOOT LID CONTROL UNIT <i>new</i>	1 S	454.00	✓
9	TAILGATE SENSOR LINE <i>new</i>	1 S	228.00	✓
10	CABLE TIE TERMINAL SOCKET <i>new</i>	1 S	3.00	✓
11	AERIAL FOR KESSY <i>new</i>	1 S	120.00	✓
12	REAR LIGHT REFLECTOR - INNER / OUTER LH <i>new</i>	2 S	80.00	✓
13	TAIL LIGHT - LH INNER <i>crackd</i>	1 S	1,401.00	✓ 1,120.80
14	TAIL LIGHT TRIM - LH INNER <i>new cut</i>	1 S	49.00	✓ 39.20
15	TAIL LIGHT - LH OUTER <i>cut</i>	1 S	1,401.00	✓ 1,120.80
16	TAIL LIGHT TRIM - LH OUTER <i>cut</i>	1 S	34.00	✓ 26.48
17	TAIL LIGHT CLUSTER CHROME - LH <i>new</i>	1 S	54.00	✓ 42.80
18	REAR BUMPER REINFORCEMENT BEAM <i>Distd</i>	1 S	1,076.00	✓ 860.80
19	REAR BUMPER SEAL - LH / RH <i>new</i>	2 S	32.00	✓ 25.60
20	REAR BUMPER GUIDE SECTION - LH / RH LOWER <i>new</i>	2 S	142.00	✓
SUB TOTAL SPARE PARTS		:	\$ 10,160.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 9638 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR BUMPER GUIDE SECTION - LH / RH UPPER <i>not in</i>	2	S 102.00	x
22	REAR BUMPER LOCKING MECHANISM <i>not in</i>	2	S 29.00	x
23	REAR BUMPER HOLDING STRAP - CENTER <i>Rec</i>	1	S 133.00	✓ 106.00
24	REAR BUMPER GUIDE PROFILE - LH NEC	1	S 75.00	✓ 59.36
25	REAR BUMPER GUIDE SECTION - CENTER <i>cracked</i>	1	S 119.00	✓ 94.80
26	REAR PARKING AID SENSOR <i>Not rec</i>	3	TBC	x
27	REAR PARKING AID SENSOR SEAL RING <i>not in</i>	4	S 10.00	x
28	REAR BUMPER WIRING SET <i>not in</i>	1	S 544.00	x
29	REAR LID <i>Dented</i>	1	S 4,142.00	✓ 3,313.60
30	REAR PACKING ADHESIVE <i>not in</i>	1	S 21.00	✓ 16.72
31	REAR LID HINGE - LH / RH <i>not in</i>	2	S 510.00	x
32	REAR LID ATTACHMENT PARTS	1	S 185.00	x
33	REAR LID LOCK ACTUATOR	1	S 1,414.00	✓
34	REAR LID LOCK	1	S 292.00	✓
35	REAR LID LOCK FLAP COVER CAP	1	S 8.00	x
36	REAR LID LOCK STRIKER	1	S 37.00	✓
37	REAR LID FLAP GASKET	1	S 266.00	✓
38	AUDI EMBLEM	1	S 144.00	✓ 114.80
39	A6 EMBLEM	1	S 104.00	✓ 82.80
40	TAILGATE CHROME TRIM STRIP - CENTER <i>Not in</i>	1	S 391.00	✓ 312.80
SUB TOTAL SPARE PARTS		:	\$ 8,526.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 9638 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR END PANEL <i>Dented.</i>	1	\$ 560.00	<i>+</i> 448.00
42	REAR END PANEL REINFORCEMENT <i>Repair</i>	1	\$ 1,128.00	<i>X</i>
43	REAR END PANEL TRIM <i>new</i>	1	\$ 310.00	<i>X</i>
44	REAR SILENCER INTERMEDIATE <i>new</i>	1	\$ 2,260.00	<i>X</i>
45	DUAL CLIP <i>new</i>	1	\$ 68.00	<i>+</i>
46	CENTER SILENCER HEAT SHELF <i>new</i>	1	\$ 155.00	<i>X</i>
47	REAR SILENCER HEAT SHIELD - LH <i>new</i>	1	\$ 98.00	<i>+</i>
48	REAR NO PLATE <i>new</i>	S/N	\$ 60.00	<i>+</i>
49	ARYLIC SEALANT <i>new</i>	S/N	\$ 180.00	<i>?</i>
50	CAVITY WAX <i>new</i>	S/N	\$ 140.00	<i>?</i>
51	STONE CHIP <i>new</i>	S/N	\$ 180.00	<i>?</i>
52	METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00	<i>?</i>
53	SUNDRIES <i>new</i>		\$ 400.00	<i>4768</i> 97.68
TOTAL SPARE PARTS		:	\$ 24,505.00	
TOTAL LABOUR CHARGES		:	\$ 11,212.00	
GRAND TOTAL		:	\$ 35,717.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

◆ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adam Lj
SURVEYED DATE : 14/06/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 08 Days (Without End Panel Replacement)

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: