

ASS. REC. BY:

REF:

MSG/22003618/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SMA 8214M

Policy No. 30001962396

Claims No. 276481

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$13,500

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/9/22 Lump Sum \$3300 confirmed by email (Red 9258.58, 73%)

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 16/9/22-typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

P. Extras

Others

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Report Format : Merimen

Lump Sum I.B.H. (\$ 3300

Veh No:

CBB 6220H

Yr Regn:

08, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

c.c

2497

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

242147

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMFWBH 7JR 94169865

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size:

F:

215/70R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/6/22

D.O.I.

14/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear OK

The U/C / Chassis frame / Body Structure affected due to collision.

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 200820153N

Date : 13 / 06 / 2022

ESTIMATE COSTS OF REPAIR

M/s C H Automotive Services

C/o 160 Sin Ming Drive

#05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : GBB 6220 H - Hyundai H1 Starex Van 2.5
Accident date : 10 / 06 / 2022

*Not Authorized
21 Rm &
Murray After Paving
5 days*

Quantity	Descriptions	Amount (S\$)
1	1 pc tail gate	\$ 2,620.40 X
2	1 pc tail gate weather strip	\$ 136.00 X
3	2 pcs tail gate hinge 1 @ 120.00	\$ 240.00 X
4	2 pcs tail gate damper 1 @ 93.40	\$ 186.80 X
5	1 pc tail gate inner trim board	\$ 297.20 X
6	1 pc tail gate inner lock	\$ 84.00 X
7	1 pc rear bumper	\$ 468.60 ✓
8	10 pcs rear bumper clips 1 @ 3.00	\$ 30.00 ✓
9	1 pc rear bumper reinforcement	\$ 347.00 ?
10	1 pc o/s rear bumper top garnish	\$ 158.00 X
11	2 pcs rear bumper bracket 1 @ 22.00	\$ 44.00 X
12	1 pc rear bumper sponge	\$ 74.30 ?
13	1 pc o/s rear bumper side retainer	\$ 22.00 ✓
14	1 pc o/s rear bumper side retainer -- 2	\$ 22.00 ✓
15	1 pc o/s rear bumper side cover	\$ 95.30 ✓
16	1 pc o/s rear bumper mudflat	\$ 22.00 ✓
17	1 pc o/s rear fender	\$ 1,640.20 ✓
18	1 pc o/s rear fender inner panel	\$ 980.20 X
19	1 pc o/s rear fender air duct	\$ 133.10 X
20	1 pc o/s rear fender inner garnish	\$ 611.20 X
21	2 pcs tail lamp 1 @ 385.00	\$ 770.00 ✓
22	1 pc o/s tail lamp panel	\$ 233.00 X
23	1 pc rear end panel	\$ 270.10 X
	Balance B/FD	\$ 9,485.40

M/sun

ols

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 200820153N

		Balance C/FD	\$ 9,485.40
24	1 pc	rear number plate lamp	\$ 26.00 X
25	1 pc	rear 'HYUNDAI' sticker	\$ 30.20 X
26	1 pc	rear 'H1' sticker	\$ 26.30 X
27	1 pc	rear Hyundai logo	\$ 26.20
			\$ 9,594.10
		Less 20 %	\$ 1,918.82
			\$ 7,675.28
28	1 pc	rear windscreen glass inner seal	\$ 60.00 sn X
29	1 pc	rear windscreen glass inner gum	\$ 60.00 sn X
30	1 set	rear bumper sensor	\$ 350.00 sn X
31	1 pc	o/s rear wheel rim	\$ 398.30 sn X
32	1 pc	o/s rear wheel tyre	\$ 385.00 sn X
33	1 pc	rear 70km/h sticker	\$ 50.00 sn 125N
34	1 set	rear '8 pax' sticker	\$ 50.00 sn 125N
35	1 pc	rear no. plate	\$ 30.00 sn X
		Balance C/FD	\$ 9,058.58
		Labour charges	\$ 1,600.00 7001
		To putty and spray painting	\$ 1,200.00 5501
		Re-seal anti rust	\$ 200.00 301
		To check wiring	\$ 120.00 201
		To check wheel alignment	\$ 80.00 X
		Remove and refix reverse sensor	\$ 120.00 501
		Remove and refix upholstery, cushion seat, garnish carpet etc	\$ 180.00 801
			\$ 12,558.58
		Plus 7% GST	\$ 879.10
		Sub-Total	\$ 13,437.68

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Page 2 of 2

Da