



簡福星噴漆工廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 221466-000
GST Reg. No. M9-0005333-E

(SUPPLEMENTARY)

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001401006	Date of Loss:	12/06/2022
Vehicle Reg. No.:	SKS778J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THIAM SENG QIAN LEW'S BENEDICT		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	12/10/2010
Vehicle Colour:	METALLIC PEARL WHITE	Chassis No:	WDD2073472F046588
Engine No:	27186030059890		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	852.50
Miscellaneous Items	0.00
Labour	350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,202.50
+ GST 7.00% (\$\$)	84.18
Nett Amount (\$\$)	1,286.68
+ Previous Estimates (\$\$)	15,044.74
Claim Total (\$\$)	16,331.42

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)
 Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:06
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER FOGLAMP LH <i>cracked</i>	0.00	0.00	*250.00 F ✓
2	1		*FRONT BUMPER SDIE RETAINER <i>new</i>	0.00	0.00	*12.00 F ✓
3	1		*BRACING (2078880190) <i>damaged</i>	0.00	0.00	*32.00 F ✓
4	1		*RADIATOR PIN <i>new</i>	0.00	0.00	*8.00 F ✓
5	1		*RADIATOR MOUNTING <i>damaged</i>	0.00	0.00	*16.00 F ✓
6	1		*FRONT AIR INTAKE COVER <i>damaged</i>	0.00	0.00	*72.00 F ✓
7	1		*SAFTY HOOK <i> Bent</i>	0.00	0.00	*38.00 F ✓
8	1		*FRONT BONNET HINGE RH <i> Bent</i>	0.00	0.00	*78.00 F ✓
9	1		*FRONT BONNET HINGE LH <i> Bent</i>	0.00	0.00	*78.00 F ✓
10	1		*FRONT BUMPER WIPER NOZZLE COVER SPRING <i>damaged</i>	0.00	0.00	*9.00 F ✓
11	1		*SIDE BRACKET RH <i> new</i>	0.00	0.00	*16.00 F ✓
12	1		*SIDE BRACKET LH <i> new</i>	0.00	0.00	*16.00 F ✓
13	1		*FRONT BUMPER SENSOR WIRE <i>snapped</i>	0.00	0.00	*150.00 F ✓
Sub Total (\$\$)						775.00
+ Margin on L,N Items 10.00% (\$\$)						77.50
Total Parts (\$\$)						852.50

F=Franchise part.

Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:06. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Adrian King
Sl/S.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO COLOUR HEADLAMP INTERIOR (OWNERS WORKSHOP) <i>Nec</i>	New	350.00 ✓
Gross Labour Cost (\$\$)			350.00

Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian King.
Slip.



簡福星嘢嘢工廠
KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 221466-006
GST Reg. No. M9-0001333-E

(SUPPLEMENTARY)

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001401006	Date of Loss:	12/06/2022
Vehicle Reg. No.:	SKS778J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THIAM SENG QIAN LEWIS BENEDICT		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	12/10/2010
Vehicle Colour:	METALLIC PEARL WHITE		
Engine No:	27186030059890	Chassis No:	WDD2073472F046588
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	682.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	682.00
+ GST 7.00% (\$\$)	47.74
Nett Amount (\$\$)	729.74
+ Previous Estimates (\$\$)	16,331.42
Claim Total (\$\$)	17,061.16

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)
Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:11
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*INTERCOOLER <i>Dented</i>	0.00	0.00	*620.00 F ✓
F=Franchise part.						
Sub Total (S\$)						620.00
+ Margin on L,N Items 10.00% (S\$)						62.00
Total Parts (S\$)						682.00

Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Adrian Ling
Sl. S.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SKS778J/23/06/2022 18:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >