

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Sep 2022)
Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SKS778J/09/09/2022 15:36
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET ABSORBER RH <i>3 paid</i>	0.00	0.00	*63.00 F ✓
2	1		*FRONT BONNET ABSORBER LH	0.00	0.00	*63.00 F ✓
3	1		*FRONT FENDER GARNISH MOULDING RH <i>cut</i>	0.00	0.00	*28.00 F ✓
4	1		*ROCKER PANEL MOULDING <i>clips</i>	0.00	0.00	*50.00 F ✓
5	1		*FRONT BUMPER WIPER COVER RH <i>new</i>	0.00	0.00	*40.00 F ✓
F=Franchise part.						
Sub Total (S\$)						244.00
+ Margin on L,N Items 10.00% (S\$)						24.40
Total Parts (S\$)						268.40

Kan Fook Sing Motor Workshop/SKS778J/09/09/2022 15:36. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DO WHEEL ALIGNMENT	New	100.00 ✓
2	HEADLAMP BLACKOUT PAINTING	New	350.00 ✓
3 new. repeated			
KFS			
Gross Labour Cost (\$\$)			450.00

Kan Fook Sing Motor Workshop/SKS778J/09/09/2022 15:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >