

Not Authorized
Return Bypass

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5295Y

AAD2202-006

2788.95

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

13 JUN 2022

SHC5295Y

JTDKB3FU403092677

200303878K

TOYOTA

PRIUS GEN 4

29/01/2022

LONPAC/XE952S

30/11/2020

PART

LIST

1	PANEL SUB-ASSY, REAR DOOR, RH	\$	1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	193.50	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	97.40	X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	293.00	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	206.70	X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	34.90	—
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	15.40	—
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	21.90	—
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	98.90	X
1	PANEL SUB-ASSY, QUARTER, RH	\$	871.50	✓
1	LINER, REAR WHEEL HOUSE, RH	\$	139.80	X
1	RIM	\$	1,900.10	X
1	COVER, REAR BUMPER	\$	SVC 485.60	X
TOTAL		\$	6,666.70	
25%		\$	1,666.68	
		\$	5,000.03	

Special Nett

1	REAR FENDER LINER CLIP	\$	65.00	X
1	REAR BUMPER RETAINER CLIP	\$	75.00	X
1	DOOR STICKER TRANSCAB	\$	100.00	born
1	HUB CAP	\$	211.50	X

Trans-cab Auto Services Pte Ltd**AAD2202-006**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5295Y

1 TYRE	\$	<i>Bh</i> 300.00	X
1 DOOR TRIM CLIP	\$	<i>nn</i> 75.00	X
1 DOOR WEATHERSTRIP CLIP	\$	<i>nn</i> 80.00	X
TOTAL	\$	906.50	

TOTAL PARTS \$ 5,906.53**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>300</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>500</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>400</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
TOTAL	\$	5,100.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5295Y

AAD2202-006

Over All Total \$ 11,006.53

(PART-BY-PART) Repair Days

~~20 Days~~

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: