



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22005622/Rqy3e2	
			Date: 09/11/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 3579M	Veh. Inspected	SNE 1505L	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/06/22/5031	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	14/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COROLLA ALTIS HYBRID ELEGANCE	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	MR2BZ3BEX00008902	Colour	GREY	
Odometer	24626 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	DUNLOP	6 mm	
L/H Front Tyre	225/45 R17	DUNLOP	6 mm	
R/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/06/2022	Inspection Date	14/06/2022	
Survey held at	60 JALAN LAM HUAT, CARROS CENTRE #05-68			
Repairer	MY CAR CONSULTANT PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>6 Working Days</b>	