



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896
HP: 98888885

Estimation

Date: 13/6/2022

Vehicle: SNE1505L

Make / Model: TOYOTA ALTIS

INS: FIRST CAPITAL

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BOOTLID <i>bt</i>	1	\$ 1,125.00	\$ 1,125.00
2	BOOTLID INNER TRIM <i>Xan</i>	1	\$ 359.00	\$ 359.00
3	<i>2388 110</i> BOOTLID REFLECTOR C/W CHROME <i>?cm</i>	2	\$ 456.00	\$ 912.00
4	BOOTLID TOP LOCK <i>? Xan</i>	1	\$ 398.00	\$ 398.00
5	BOOTLID OUTER CHROME MOULDING <i>?cm</i>	1	\$ 312.00	\$ 312.00
6	BOOTLID WEATHER STRIP <i>an</i>	1	\$ 220.00	\$ 220.00
7	BOOTLID LOGO <i>an</i>	1	\$ 74.00	\$ 74.00
8	BOOTLID EMBLEM 'ALTIS' <i>an</i>	1	\$ 65.00	\$ 65.00
9	BOOTLID SENSOR <i>? Xan</i>	1	\$ 312.00	\$ 312.00
10	BOOTLID EMBLEM 'COROLLA' <i>an</i>	1	\$ 65.00	\$ 65.00
11	TAILAMP C/W CHROME <i>? Xan</i>	2	\$ 612.00	\$ 1,224.00
12	TAILAMP LOWER PANEL <i>Xan</i>	2	\$ 322.00	\$ 644.00
13	REAR BUMPER <i>de</i>	1	\$ 698.00	\$ 698.00
14	REAR BUMPER SIDE RETAINER <i>Xan</i>	2	\$ 112.00	\$ 224.00
15	REAR BUMPER BRACKET <i>Xan</i>	2	\$ 168.00	\$ 326.00
17	REAR BUMPER REINFORCEMENT <i>?bt</i>	1	\$ 395.00	\$ 395.00
18	REAR BUMPER REFLECTOR <i>Xan</i>	2	\$ 112.00	\$ 224.00
19	REAR BUMPER UNDERCOVER <i>Xan</i>	1	\$ 315.00	\$ 315.00
20	REAR FENDER COWLING <i>Xan</i>	2	\$ 358.00	\$ 716.00
21	REAR FENDER INNER TRIM <i>Xan</i>	2	\$ 398.00	\$ 796.00
22	REAR END PANEL <i>bt</i>	1	\$ 695.00	\$ 695.00
23	END PANEL TOP GARNISH <i>?de</i>	1	\$ 278.00	\$ 278.00
24	REAR FLOOR PANEL <i>Xan</i>	1	\$ 1,025.00	\$ 1,025.00
25	REAR SPARE TYRE TOP BOARD <i>?de</i>	1	\$ 357.00	\$ 357.00
26	REAR EXHAUST PIPE <i>Xan</i>	1	\$ 951.00	\$ 951.00
				\$ 12,710.00
			Less 25%	\$ 3,177.50
			Total	\$ 9,532.50

933.30

276.20

186.50

542

316

226.70

4469.70
259
3352.27

S/Nett items:				
1	REAR NUMBER PLATE <i>Xan</i>	1	\$ 50.00	\$ 50.00
2	BOOTLID INSULATOR CLIPS <i>an</i>	1	\$ 30.00	\$ 30.00
3	TAILAMP CLIPS SET <i>an</i>	1	\$ 40.00	\$ 40.00
4	REAR FENDER SEALANT <i>Xan</i>	1	\$ 150.00	\$ 150.00
5	REAR FENDER COWLING CLIPS SET <i>Xan</i>	1	\$ 50.00	\$ 50.00
6	REAR FENDER INNER TRIM CLIPS SET <i>Xan</i>	1	\$ 50.00	\$ 50.00
7	REAR WINDSCREEN SEALANT <i>Xan</i>	1	\$ 80.00	\$ 80.00
8	REAR WINDSCREEN INNER SEAL <i>Xan</i>	1	\$ 80.00	\$ 80.00

9	REAR END PANEL TOP GARNISH CLIPS	1	\$ 30.00	\$ 30.00
10	REAR END PANEL SEALANT	1	\$ 120.00	\$ 120.00
11	REAR SPARE TYRE PANEL SEALANT	1	\$ 150.00	\$ 150.00
16	REAR BUMPER SENSOR	1	\$ 200.00	\$ 200.00
12	REVERSE CAMERA	1	\$ 400.00	\$ 400.00
				\$ 3,060.00
	Labour to:			
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,600.00	\$ 1,600.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,600.00	\$ 1,600.00
3	REMOVE AND REFIT UPHOLSTERY, SEAT	1	\$ 350.00	\$ 350.00
4	REMOVE AND REFIR REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
5	REMOVE AND REFIR REAR BOOTLID MECHANISM	1	\$ 100.00	\$ 100.00
6	REMOVE AND REFIR REAR EXHAUST SYSTEM	1	\$ 150.00	\$ 150.00
7	REMOVE AND REFIR FUEL TANK ASSY	1	\$ 150.00	\$ 150.00
8	REAR CHASSIS ALIGNMENT	1	\$ 200.00	\$ 200.00
9	TO CHECK ELECTRICAL WIRING	1	\$ 100.00	\$ 100.00
10	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 50.00	\$ 50.00
				\$ 4,450.00
			Parts Replacement Amount	\$ 12,592.50
			Total Amount for Labour	\$ 4,450.00
			Total Amount	\$ 17,042.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3352.27

120.00

1580.00

5052.27

20%

4041.82

4/s - \$4,050

Rame

#p 90010068

6 days

4/s

14/06/22 @ 1520

Reey after repair