

## Vehicle Damage Assessment Report for [YN787T]

Estimate Created: 15/07/2022 04:10 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 27/07/2022 02:45 by LKK\_cs-a (LKK\_Auto\_Consultants\_Pte\_Ltd)

### General Information

|                   |                              |                  |                 |
|-------------------|------------------------------|------------------|-----------------|
| Insurance Company | III                          | Claim Number     | MPC2022D0003201 |
| Claim Type        | TP                           |                  |                 |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |                 |

### Vehicle Information

|                      |            |                    |      |
|----------------------|------------|--------------------|------|
| Brand                | Mitsubishi | Model              | L300 |
| Engine Type          | 1KDFTV     |                    |      |
| License Plate Number | YN787T     | VIN (or Chassis #) |      |

### Vehicle Condition

|                 |                 |                       |
|-----------------|-----------------|-----------------------|
| Damaged Diagram | Odometer        | 174,204.00 Km         |
|                 | Tyres Condition |                       |
|                 | Front Left      | OTHER 7.00 R16 6.0 mm |
|                 | Front Right     | OTHER 7.00 R16 6.0 mm |
|                 | Rear Left       | OTHER 7.00 R16 6.0 mm |
|                 | Rear Right      | OTHER 7.00 R16 6.0 mm |

### Comments

|                                                                                                                            |                                 |
|----------------------------------------------------------------------------------------------------------------------------|---------------------------------|
| - Final review with information provided by LKK: Concluded the cost of repair at lump sum \$3500.00 with 3 days for repair | Insurlogic 1 (27/07/2022 02:44) |
|----------------------------------------------------------------------------------------------------------------------------|---------------------------------|

**Parts**

| Description           | Number/Type | Qty | Cost    | Markup/Disc. % | Sum      |
|-----------------------|-------------|-----|---------|----------------|----------|
| FRONT BUMPER          |             | 1   | 1084.39 | -25.00 %       | 813.29   |
| HEADLAMP LH           |             | 1   | 492.21  | -25.00 %       | 369.16   |
| FRONT SIDE LAMP LH    |             | 1   | 303.50  | -25.00 %       | 227.63   |
| FRONT SIGNAL LAMP LH  |             | 1   | 208.02  | -25.00 %       | 156.02   |
| FRONT DOOR PANEL LH   |             | 1   | 1910.15 | -25.00 %       | 1,432.61 |
| FRONT STEP GARNISH LH |             | 1   | 311.00  | -25.00 %       | 233.25   |

Parts Subtotal 3,231.96

**Labor****Replace/RnR**

| Description                       | Type | Cost   | Markup/Disc % | Price  |
|-----------------------------------|------|--------|---------------|--------|
| CHECK WIRING                      | RnR  | 20.00  | 0.00 %        | 20.00  |
| TRANSFER FRONT DOOR MECHNISM LH   | RnR  | 60.00  | 0.00 %        | 60.00  |
| REPLACE FRONT BUMPER AND LAMPS LH | RnR  | 200.00 | 0.00 %        | 200.00 |
| REPLACE FRONT DOOR LH             | RnR  | 100.00 | 0.00 %        | 100.00 |
| SUPPLY AND REPLACE STICKER        | RnR  | 380.00 | 0.00 %        | 380.00 |
| ANTI RUST                         | RnR  | 30.00  | 0.00 %        | 30.00  |

**Paint**

| Description   | Paint Type | Cost   | Markup/Disc % | Price  |
|---------------|------------|--------|---------------|--------|
| FRONT BUMPER  | Full spray | 200.00 | 0.00 %        | 200.00 |
| FRONT DOOR LH | Full spray | 200.00 | 0.00 %        | 200.00 |

Labor Rate S\$ 50 / Hour

General Labor Subtotal 790.00

Paint Labor Subtotal 400.00

Labor Subtotal 1,190.00

**Summary**

|                |          |
|----------------|----------|
| Repair Cost    | 4,421.96 |
| Discount(21 %) | (921.95) |
|                | 3,500.01 |
| Excess         | (0.00)   |
| GST(0.00 %)    | 0.00     |
| Grand Subtotal | 3,500.01 |