

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22005628/RPA3Q2**Date:** 18/01/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900263012-01
Claimant Vehicle No :	SHB1270A	Insured Vehicle No :	SMR2791M
Date of Loss:	05/06/2022	Nature of Claim:	TP
		Claim No:	3896079035SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB1270A	Engine No:	HIDDEN
Make & Model:	M.G. MG5, EV EXCITE T (M)	Chassis No:	LSJE24031MG057756
Reg. Date:	29/10/2021 (Man. Year: 2021)	Odometer:	26252 km
Colour:	Green		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,005.68	21.60	4,984.08	99.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,849.00	940.00	4,909.00	83.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,854.68	961.60	9,893.08	91.14
	+ Loss of Use (3.5 x S\$50.00/day) (S\$)	175.00		
	+ Car Rental (3.5 x S\$114.49/day) (S\$)	400.72		
	+ Doc/Search Fee (S\$)	7.00		
	Nett Liability (S\$)	1,544.32		
	Global Sum Settlement (S\$)	1,500.00		

INSPECTION

Date of Assignment:	08/06/2022	
Date Inspected:	08/06/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STICKER ELECTRIC (LOGO) (SN)	Necessary	21.60 F	*21.60 F
2	1		*FASCIA -RR BPR	Not Necessary	758.48 F	*- F
3	1		*BRACKET -RR BPR FASCIA SI MTG -RH	Not Necessary	46.08 F	*- F
4	1		*LINER ASM -RR W/H PNL -RH	Not Necessary	85.48 F	*- F
5	1		*WINDOW ASM -QTR RH	Not Necessary	251.48 F	*- F
6	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
7	1		*CHECK ASM -RR S/D RH	Not Necessary	21.00 F	*- F
8	1		*HINGE ASM -RR S/D UPR -RH	Not Necessary	46.90 F	*- F
9	1		*HINGE ASM -RR S/D LWR -RH	Not Necessary	47.22 F	*- F
10	1		*COVER -RR S/D LK CYL-RH	Not Necessary	14.88 F	*- F
11	1		*STRIKER -FRT S/D LK	Not Necessary	16.74 F	*- F
12	1		*REGULATOR ASM -RR S/D WDO -RH	Not Necessary	265.30 F	*- F
13	1		*LATCH ASM -RR S/D -RH	Not Necessary	139.98 F	*- F
14	1		*MOLDING ASM -RR S/D WDO UPR RVL -RH	Not Necessary	54.50 F	*- F
15	1		*PANEL -BODY SI OTR RR FENDER -RH	Repair	977.08 F	*- F
16	1		*DOOR ASM -RR SI -RH	Repair	2,185.04 F	*- F
17	1		*HANDLE ASM -FRT S/D O/S -RH	Repair	36.92 F	*- F

F=Franchise part.

Total Parts (\$\$) **5,005.68** **21.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK	New	3,600.00	200.00
2	SPRAY PAINT	New	1,284.00	440.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
4	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
5	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	150.00
6	ISOLATED OF (EV)	New	150.00	150.00
7	TO REMOVE & REFIT REAR QUARTER GLASS RH	New	120.00	0.00
8	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM	New	125.00	0.00
			Gross Labour Cost (S\$)	5,849.00
				940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >