

Section A - Accident Details

Registration Number	SHB1270A
Case Reference Number	TAX/06/22/2011
Registration Date	29/10/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	JAHFRI BIN ABDULLAH
Type of Accident	Side Swipe
Accident Date and Time	5/6/2022 11:15 AM
Accident Reported Date and Time	6/6/2022 8:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115220
Special Instruction to ARC, if any	TP
Prepared Date and Time	6/6/2022 5:00 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,600.00	\$200.00
Total Spray Cost	\$1,284.00	\$440.00
Total Spare Part Cost	\$4,510.97	\$21.60
Total Other Cost	\$965.00	\$300.00
TOTAL COST	\$10,359.97	\$961.60 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	08/06/2022 2:45 PM	08/06/2022 4:27 PM
Signature	<input type="text"/>	<input type="text"/>
Remarks		RESURVEY AFTER REPAIR

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2206-0187	Invoice Number	
Quotation Date	17.06.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$3,600.00	\$200.00 ✓
Total Labour	\$3,600.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RH REAR DOOR	\$428.00	\$220.00 ✓
TO RESPRAY REAR FENDER RH	\$428.00	\$220.00 ✓
TO RESPRAY REAR BUMPER	\$428.00	\$0.00
Total Spray Painting & Panel Beating	\$1,284.00	\$440.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00 ✓
ISOLATED OF (EV) (NET)	\$150.00	\$150.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
Total Other Costs	\$965.00	\$300.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10369261-SPRP	FASCIA-RR BPR	0.00	\$758.48	0.00	\$0.00	Replace	Not Given
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	0.00	\$46.08	0.00	\$0.00	Replace	Not Given
		10720690 CC-SEPP	PANEL-BODY SI OTR RR FENDER - RH	1.00	\$977.08	100.00	\$0.00	Replace	Repair
			STICKER ELECTRIC (LOGO)	1.00	\$21.60	0.00	\$21.60	Replace	Replace
		10626941	LINER ASM-RR W/H PNL -RH	0.00	\$85.48	0.00	\$0.00	Replace	Not Given
		10322238	WINDOW ASM-QTR - RH	0.00	\$251.48	0.00	\$0.00	Replace	Not Given
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given
		10380138-SEPP	DOOR ASM-RR SI -RH	1.00	\$2,185.04	100.00	\$0.00	Replace	Repair
		10383922	CHECK ASM-RR S/D -RH	0.00	\$21.00	0.00	\$0.00	Replace	Not Given
		10364952-SEPP	HINGE ASM-RR S/D UPR-RH	0.00	\$46.90	0.00	\$0.00	Replace	Not Given
		10364954-SEPP	HINGE ASM-RR S/D LWR-RH	0.00	\$47.22	0.00	\$0.00	Replace	Not Given
		10285737-SPRP	HANDLE ASM-FRT S/D O/S - RH	1.00	\$36.92	100.00	\$0.00	Replace	Repair
		10285746-SPRP	COVER-RR S/D LK CYL-RH	0.00	\$14.88	0.00	\$0.00	Replace	Not Given
		10246254	STRIKER-FRT S/D LK	0.00	\$16.74	0.00	\$0.00	Replace	Not Given
		10760960	REGULATOR ASM-RR S/D WDO-RH	0.00	\$265.30	0.00	\$0.00	Replace	Not Given

X NN
X NN
R
✓ NEC
X NN
X NN
X NN
R
X NN
X NN
X NN
R
X NN
X NN
X NN
X NN

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/06/2022

User ID : angbangkien

		10297708	LATCH ASM-RR S/D -RH	0.00	\$139.98	0.00	\$0.00	Replace	Not Given
		10374913	MOLDING ASM-RR S/D WDO UPR RVL-RH	0.00	\$54.50	0.00	\$0.00	Replace	Not Given
Total					\$5,005.68		\$21.60		

X NN
X NN

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

21.60
+ 200.00
+ 740.00

961.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: