



VEHICLE NO: SKL9902U

MAKE &amp; MODEL: AUDI A4.

AUTO / MANUAL

DATE OF ACCIDENT	11 / 06 / 22.	CC 1.4.
TIME OF ACCIDENT	0335.	AM / PM
LOCATION OF ACCIDENT	BUKIT TIMAH RD RFF FOURTH AVE.	
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE	
NAME OF OWNER	NG ZI YANG, STANLEY JAMES (HUANG ZIYANG).	
EMAIL	CITIZENPOWER555@GMAIL.COM	Office: MOBILE: 93687885.
NRIC	58587104E.	
CLAIM TYPE	OD / THIRD PARTY / REPORTING ONLY	
FLEET POLICY	YES / NO?	
INSURANCE CO.	TOKIO MARINE	
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft	
POLICY NO.	22-MT000490-R04	
NAME OF DRIVER	AS ABOVE / IF NO: "	
NRIC	"	
DATE OF BIRTH	04 / 11 / 85.	
ANY PASSENGER	YES / NO: - DRIVER ONLY.	
NAME OF PASSENGER	-	
GENDER OF PASSENGER	MALE / FEMALE	
OCCUPATION	Outdoor / Indoor	
DATE OF DRIVING PASS	17 / 08 / 2005.	
GENDER	Male / Female	
CONTACT NO.	Mobile: " Office: Home:	
EMAIL	"	
ADDRESS	66 TOM TUCK ROAD, #07-15, S'PORE 596730	
DOES DRIVER OWN OTHER VEHICLES?	NO / If yes: Reg No. INSURER -	
RELATIONSHIP	Employee / If No: SELF.	
WEATHER CONDITION	Clear / Raining / Other:	
ROAD SURFACE	Dry / Wet / Other:	
ANY INJURIES	No / If yes: Who? DRIVER.	
CONTACT NO.		
POLICE REPORT	No / If yes: Where?	
NOTICE OF INTENDED PROSECUTION GIVEN?	NO / IF YES: WHO?	
VEHICLE B NO.	SJT 4226 R. Any Passenger: 1 DRIVER.	
NAME	KAREINA LAU	
CONTACT NO.	97898353	
VEHICLE C NO.	SLU 6617 D. Any Passenger: 1 DRIVER 1 PASSENGER.	
VEHICLE D NO.	Any Passenger:	
VEHICLE E NO.	Any Passenger:	
VEHICLE F NO.	Any Passenger:	
ANY WITNESS		
WITNESS CONTACT NO.		
WAS THERE ANY VIDEO CAPTURE?	YES / NO	
WAS THERE ANY AUDIO RECORDED?	YES / NO	



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


  
16/06/2022  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan

UKIT TIMAH RD (TWO'S LANE RIVER BRIDGE)



A: SKL9902U  
16/06/2022


**Describe Circumstances of the Accident**

On the stated date and time, I was travelling along bukit timah road.

I stopped my car behind vehicle C. Suddenly vehicle B hit onto the rear of my vehicle and caused my vehicle to surge forward and hit onto vehicle C.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

 19:34  
12/6/2022



## BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

### Repair Estimate

Vehicle number: SKL9902U

Make & Model: Audi A4

Chassis number: WAUZZZF40HA165397

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ <del>bf</del> 3,264.00
2	Bonnet RH hinge	1	\$ <del>x</del> 305.00
3	Bonnet LH hinge	1	\$ <del>x</del> 305.00
4	Bonnet RH lock	1	\$ <del>x</del> 214.00
5	Bonnet RH lock catch	1	\$ <del>x</del> 48.00
6	Bonnet LH lock	1	\$ <del>x</del> 214.00
7	Bonnet LH lock catch	1	\$ <del>x</del> 48.00
8	Bonnet inner heat shield	1	\$ <del>x</del> 351.00
9	Bonnet inner heat shield clips	1set	\$ <del>x</del> 80.00
10	Bonnet impact protection RH	1	\$ <del>x</del> 25.00
11	Bonnet impact protection LH	1	\$ <del>x</del> 25.00
12	Bonnet impact protection centre	1	\$ <del>x</del> 28.00
13	Bonnet RH absorber stay	1	\$ <del>x</del> 232.00
14	Bonnet LH absorber stay	1	\$ <del>x</del> 232.00
15	Bonnet bowden cable centre	1	\$ <del>x</del> 58.00
16	Bonnet release cable	1	\$ <del>x</del> 72.00
17	Bonnet release lever	1	\$ <del>x</del> 23.00
18	Front bumper	1	\$ <del>cy</del> 1,946.00
19	Front bumper clips	1set	\$ <del>cy</del> 80.00
20	Front bumper reinforcement	1	\$ <del>bf</del> 845.00
21	Front bumper sponge	1	\$ <del>x</del> 118.00
22	Front bumper inner sponge	1	\$ <del>x</del> 125.00
23	Front bumper RH air guide	1	\$ <del>x</del> 59.00
24	Front bumper RH air guide grille	1	\$ <del>x</del> 128.00
25	Front bumper lower grille	1	\$ <del>cy</del> 196.00
26	Front bumper LH air guide	1	\$ <del>x</del> 59.00
27	Front bumper LH air guide grille	1	\$ <del>x</del> 128.00
28	Front bumper RH side retainer	1	\$ <del>x</del> 36.00
29	Front bumper LH side retainer	1	\$ <del>x</del> 36.00
30	Front bumper RH side garnish	1	\$ <del>x</del> 135.00
31	Front bumper LH side garnish	1	\$ <del>x</del> 135.00
32	Front bumper number plate garnish	1	\$ <del>ms</del> 98.00
33	Front bumper RH sensor	1	\$ <del>x</del> 242.00
34	Front bumper LH sensor	1	\$ <del>x</del> 242.00
35	Front bumper sensor ring seal	4	\$ <del>cy</del> 40.00
36	Front grille	1	\$ <del>bw</del> 1,666.00
37	Front grille clips	1set	\$ <del>cy</del> 60.00
38	RH headlamp assy	1	\$ <del>cy</del> 7,693.00

2605

x  
un

un

un

un

1010

9900

39	RH headlamp washer nozzle	1	\$ <del>X</del>	128.00	un
40	RH headlamp washer nozzle cover	1	\$ <del>X</del>	32.00	un
41	LH headlamp assy	1	\$ <del>cut</del>	7,693.00	un
42	LH headlamp washer nozzle	1	\$ <del>X</del>	128.00	un
43	LH headlamp washer nozzle cover	1	\$ <del>X</del>	32.00	un
44	Support panel	1	\$ <del>cut</del>	1,016.00	900
45	Support panel upper cover	1	\$ <del>X</del>	126.00	
46	Aircon condenser	1	\$ <del>bt</del>	722.00	
47	Aircon discharge pipe	1	\$ <del>X</del>	278.00	
48	Aircon suction pipe	1	\$ <del>X</del>	301.00	
49	Radiator assy	1	\$ <del>bt</del>	982.00	
50	Radiator fan assy	1	\$ <del>cut</del>	2,348.00	1800
51	Radiator fan ring	1	\$ <del>cut</del>	267.00	
52	Radiator RH air guide	1	\$ <del>X</del>	32.00	un
53	Radiator LH air guide	1	\$ <del>X</del>	32.00	
54	Radiator RH air inner duct	1	\$ <del>X</del>	21.00	
55	Radiator LH air inner duct	1	\$ <del>X</del>	21.00	
56	Radiator upper air guide	1	\$ <del>X</del>	18.00	
57	Radiator lower air guide	1	\$ <del>X</del>	21.00	
58	Turbo intercooler	1	\$ <del>bt</del>	782.00	
59	Front RH fender	1	\$ <del>X</del>	787.00	un
60	Front RH fender splash shield	1	\$ <del>X</del>	241.00	
61	Front RH fender splash shield clips	1set	\$ <del>X</del>	60.00	
62	Front LH fender	1	\$ <del>X</del>	787.00	
63	Front LH fender splash shield	1	\$ <del>X</del>	241.00	
64	Front LH fender splash shield clips	1set	\$ <del>X</del>	60.00	
65	Driver seat belt	1	\$ <del>cut</del>	1,103.00	un
66	Driver seat belt buckle	1	\$ <del>X</del>	171.00	
67	Passenger seat belt	1	\$ <del>cut</del>	1,103.00	
68	Passenger seat belt buckle	1	\$ <del>X</del>	171.00	
69	Rear RH passenger seat belt	1	\$ <del>X</del>	1,003.00	un
70	Rear RH passenger seat belt buckle	1	\$ <del>X</del>	167.00	
71	Rear centre passenger seat belt	1	\$ <del>X</del>	873.00	
72	Rear centre passenger seat belt buckle	1	\$ <del>X</del>	167.00	
73	Rear LH passenger seat belt	1	\$ <del>X</del>	1,003.00	un
74	Rear LH passenger seat belt buckle	1	\$ <del>X</del>	167.00	
75	Airbag crash sensor	1	\$ <del>cut</del>	201.00	
76	Airbag control unit	1	\$ <del>cut</del>	2,112.00	
77	Bootlid	1	\$ <del>bt</del>	3,253.00	
78	Bootlid centre emblem	1	\$ <del>cut</del>	138.00	
79	Bootlid "A4" emblem	1	\$ <del>un</del>	99.00	
80	Bootlid "TFSI" emblem	1	\$ <del>un</del>	99.00	
81	Bootlid RH lamp	1	\$ <del>X</del>	1,019.00	un
82	Bootlid LH lamp	1	\$ <del>X</del>	1,019.00	
83	Bootlid RH number plate lamp	1	\$ <del>X</del>	58.00	
84	Bootlid LH number plate lamp	1	\$ <del>X</del>	58.00	
85	Bootlid push button	1	\$ <del>un</del>	530.00	
86	Bootlid inner trim	1	\$ <del>X</del>	389.00	
87	Bootlid inner trim clips	1set	\$ <del>X</del>	70.00	
88	Bootlid lock	1	\$ <del>X</del>	273.00	
89	Bootlid RH hinge	1	\$ <del>X</del>	229.00	
90	Bootlid LH hinge	1	\$ <del>X</del>	229.00	
91	Bootlid weatherstrip	1	\$ <del>fw</del>	206.00	



92	Rear bumper	1	\$ <del>2,181.00</del> 2,181.00
93	Rear bumper clips	1set	\$ <del>30.00</del> 70.00
94	Rear bumper lower garnish	1	\$ <del>249.00</del> 249.00
95	Rear bumper RH reflector	1	\$ <del>45.00</del> 45.00
96	Rear bumper LH reflector	1	\$ <del>45.00</del> 45.00
97	Rear bumper RH upper retainer	1	\$ <del>23.00</del> 23.00
98	Rear bumper LH upper retainer	1	\$ <del>23.00</del> 23.00
99	Rear bumper RH lower retainer	1	\$ <del>44.00</del> 44.00
100	Rear bumper LH lower retainer	1	\$ <del>44.00</del> 44.00
101	Rear bumper reinforcement	1	\$ <del>945.00</del> 945.00
102	Rear bumper RH side reverse sensor	1	\$ <del>244.00</del> 244.00
103	Rear bumper RH centre reverse sensor	1	\$ <del>244.00</del> 244.00
104	Rear bumper LH centre reverse sensor	1	\$ <del>244.00</del> 244.00
105	Rear bumper LH side reverse sensor	1	\$ <del>244.00</del> 244.00
106	Rear bumper reverse sensor O-rings seal	4	\$ <del>48.00</del> 48.00
107	Rear bumper reverse sensor wire harness	1	\$ <del>344.00</del> 344.00
108	LH taillamp assy	1	\$ <del>1,019.00</del> 1,019.00
109	LH taillamp panel	1	\$ <del>185.00</del> 185.00
110	RH taillamp assy	1	\$ <del>1,019.00</del> 1,019.00
111	RH taillamp panel	1	\$ <del>185.00</del> 185.00
112	End panel assy	1	\$ <del>764.00</del> 764.00
113	End panel inner garnish	1	\$ <del>178.00</del> 178.00
114	End panel inner garnish clips	1set	\$ <del>2040.00</del> 2040.00
115	Rear compartment panel top cover	1	\$ <del>711.00</del> 711.00
116	Rear compartment panel	1	\$ <del>2,223.00</del> 2,223.00
117	Rear compartment panel insulator	1	\$ <del>121.00</del> 121.00
118	Rear fender RH inner trim	1	\$ <del>787.00</del> 787.00
119	Rear fender RH inner trim clips	1set	\$ <del>60.00</del> 60.00
120	Rear fender RH splash shield	1	\$ <del>132.00</del> 132.00
121	Rear fender RH splash shield clips	1set	\$ <del>30.00</del> 30.00
122	Rear fender LH inner trim	1	\$ <del>787.00</del> 787.00
123	Rear fender LH inner trim clips	1set	\$ <del>60.00</del> 60.00
124	Rear fender LH splash shield		\$ <del>132.00</del> 132.00
125	Rear fender LH splash shield clips		\$ <del>30.00</del> 30.00
126	Exhaust silencer	1	\$ <del>1,083.00</del> 1,083.00
127	Exhaust silencer heat shield	1	\$ <del>167.00</del> 167.00
128	Exhaust silencer gasket	1	\$ <del>68.00</del> 68.00
129	Rear battery cut off cable	1	\$ <del>558.00</del> 558.00

\$ 68,003.00

Parts less 5% \$ 3,400.15

Total \$ 64,602.85

No.	Special Nett Items		Amount S\$
1	Radiator coolant	1	\$ <del>95.00</del> 95.00
2	Front grille "Quattro" sticker	1	\$ <del>125.00</del> 125.00
3	Front number plate	1	\$ <del>80.00</del> 80.00
4	End panel joint sealant	1	\$ <del>70.00</del> 70.00
5	Rear compartment panel joint sealant	1	\$ <del>80.00</del> 80.00

6	RH taillamp panel	1	\$	X	35.00
7	LH taillamp panel	1	\$	X	35.00
8	Rear number plate	1	\$	X	70.00

Total: \$ 590.00

No.	Labour and painting	Amount S\$
	<b>(FRONT PORTION)</b>	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ <del>600</del> 1,800.00
2	Spray painting on affected areas and panels	\$ <del>500</del> 1,500.00
3	Check wiring and lighting system on affected areas	\$ <del>30</del> 120.00
4	Apply rust coating chemical on affected areas and panels	\$ <del>30</del> 180.00
5	Remove and replace turbo intercooler and pipes to assist repair	\$ <del>50</del> 220.00
6	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas	\$ <del>100</del> 240.00
7	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant and check leakage	\$ <del>100</del> 280.00
8	Refocus and adjust headlamps assy	\$ <del>30</del> 50.00
	<b>(REAR PORTION)</b>	
9	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ <del>900</del> 2,200.00
10	Spray painting on affected areas and panels	\$ <del>900</del> 1,800.00
11	Check wiring and lighting system on affected areas	\$ <del>30</del> 120.00
12	Apply rust coating chemical on affected areas and panels	\$ <del>30</del> 180.00
13	Remove and replace rear bumper reverse sensors and wire harness to assist repair	\$ <del>30</del> 180.00
14	Remove and replace rear inner trims, garnish and boards to assist repair	\$ <del>60</del> 450.00
15	Remove and replace bootlid mechanism to new bootlid	\$ <del>60</del> 180.00
16	Remove and replace exhaust silencer, gasket, mountings to assist repair	\$ <del>60</del> 320.00
17	Mount vehicle on chassis alignment bench to repair chassis frames	\$ <del>X</del> 550.00



18	Remove and replace battery cut-off cable to assist repair	\$ <del>K</del> 280.00
19	Reset and diagnose control unit and fault code after repair	\$ <del>150</del> 450.00
20	Remove and replace front and rear seat belts, buckles and control unit	\$ <del>100</del> 550.00

Total: \$ 11,650.00

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Spare Parts: \$ 64,602.85

Special Nett: \$ 590.00

Labour: \$ 11,650.00

**Total Amount: \$ 76,842.85**

Tanflin 97495747 check repair limit.  
 15/6/22 @ 1245  
 Resurvey photo. To check part price  
 To check consistency of accident  
 4/5 Resurvey after repair  
 Tanflin @ Llanabon  
 10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_