

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SKL9902U

Make & Model: Audi A4

Chassis number: WAUZZZF40HA165397

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ 61 3,264.00
2	Bonnet RH hinge	1	\$ x 305.00
3	Bonnet LH hinge	1	\$ x 305.00
4	Bonnet RH lock	1	\$ X 214.00
5	Bonnet RH lock catch	1	\$ X 48.00
6	Bonnet LH lock	1	\$ X 214.00
7	Bonnet LH lock catch	1	\$ X 48.00
8	Bonnet inner heat shield	1	\$ X 351.00
9	Bonnet inner heat shield clips	1set	\$ X 80.00
10	Bonnet impact protection RH	1	\$ X 25.00
11	Bonnet impact protection LH	1	\$ X 25.00
12	Bonnet impact protection centre	1	\$ X 28.00
13	Bonnet RH absorber stay	1	\$ X 232.00
14	Bonnet LH absorber stay	1	\$ X 232.00
15	Bonnet bowden cable centre	1	\$ X 58.00
16	Bonnet release cable	1	\$ X 72.00
17	Bonnet release lever	1	\$ X 23.00
18	Front bumper	1	\$ 04 1,946.00
19	Front bumper clips	1set	\$ 04 80.00
20	Front bumper reinforcement	1	\$ 61 845.00
21	Front bumper sponge	1	\$ x 118.00
22	Front bumper inner sponge	1	\$ X 125.00
23	Front bumper RH air guide	1	\$ X 59.00
24	Front bumper RH air guide grille	1	\$ X 128.00
25	Front bumper lower grille	1	\$ 04 196.00
26	Front bumper LH air guide	1	\$ X 59.00
27	Front bumper LH air guide grille	1	\$ X 128.00
28	Front bumper RH side retainer	1	\$ X 36.00
29	Front bumper LH side retainer	1	\$ X 36.00
30	Front bumper RH side garnish	1	\$ X 135.00
31	Front bumper LH side garnish	1	\$ X 135.00
32	Front bumper number plate garnish	1	\$ 04 98.00
33	Front bumper RH sensor	1	\$ X 242.00
34	Front bumper LH sensor	1	\$ X 242.00
35	Front bumper sensor ring seal	4	\$ 04 40.00
36	Front grille	1	\$ 04 1,666.00
37	Front grille clips	1set	\$ 04 60.00
38	RH headlamp assy	1	\$ 04 7,693.00

2605

x
nn

nn

nn

nn

1000

4900

39	RH headlamp washer nozzle	1	\$ X	128.00	un
40	RH headlamp washer nozzle cover	1	\$ X	32.00	un
41	LH headlamp assy	1	\$ cut	7,693.00	
42	LH headlamp washer nozzle	1	\$ X	128.00	un
43	LH headlamp washer nozzle cover	1	\$ X	32.00	un
44	Support panel	1	\$ cut	1,016.00	900
45	Support panel upper cover	1	\$ X	126.00	nn
46	Aircon condenser	1	\$ bt	722.00	
47	Aircon discharge pipe	1	\$ X	278.00	nn
48	Aircon suction pipe	1	\$ X	301.00	nn
49	Radiator assy	1	\$ bt	982.00	
50	Radiator fan assy	1	\$ cut	2,318.00	1500
51	Radiator fan ring	1	\$ cut	267.00	
52	Radiator RH air guide	1	\$ X	32.00	un
53	Radiator LH air guide	1	\$ X	32.00	
54	Radiator RH air inner duct	1	\$ X	21.00	
55	Radiator LH air inner duct	1	\$ X	21.00	
56	Radiator upper air guide	1	\$ X	18.00	
57	Radiator lower air guide	1	\$ X	21.00	
58	Turbo intercooler	1	\$ bt	782.00	
59	Front RH fender	1	\$ X	787.00	un
60	Front RH fender splash shield	1	\$ X	241.00	
61	Front RH fender splash shield clips	1set	\$ X	60.00	
62	Front LH fender	1	\$ X	787.00	
63	Front LH fender splash shield	1	\$ X	241.00	
64	Front LH fender splash shield clips	1set	\$ X	60.00	
65	Driver seat belt	1	\$ cut	1,103.00	nn
66	Driver seat belt buckle	1	\$ X	171.00	
67	Passenger seat belt	1	\$ cut	1,103.00	un
68	Passenger seat belt buckle	1	\$ X	171.00	
69	Rear RH passenger seat belt	1	\$ X	1,003.00	
70	Rear RH passenger seat belt buckle	1	\$ X	167.00	
71	Rear centre passenger seat belt	1	\$ X	873.00	
72	Rear centre passenger seat belt buckle	1	\$ X	167.00	
73	Rear LH passenger seat belt	1	\$ X	1,003.00	
74	Rear LH passenger seat belt buckle	1	\$ X	167.00	
75	Airbag crash sensor	1	\$ cut	201.00	
76	Airbag control unit	1	\$ cut	2,112.00	
77	Bootlid	1	\$ bt	3,253.00	
78	Bootlid centre emblem	1	\$ cut	138.00	
79	Bootlid "A4" emblem	1	\$ un	99.00	
80	Bootlid "TFSI" emblem	1	\$ un	99.00	
81	Bootlid RH lamp	1	\$ X	1,019.00	un
82	Bootlid LH lamp	1	\$ X	1,019.00	
83	Bootlid RH number plate lamp	1	\$ X	58.00	
84	Bootlid LH number plate lamp	1	\$ X	58.00	
85	Bootlid push button	1	\$ X	530.00	
86	Bootlid inner trim	1	\$ X	389.00	
87	Bootlid inner trim clips	1set	\$ X	70.00	
88	Bootlid lock	1	\$ X	273.00	
89	Bootlid RH hinge	1	\$ X	229.00	
90	Bootlid LH hinge	1	\$ X	229.00	
91	Bootlid weatherstrip	1	\$ un	206.00	

92	Rear bumper	1	\$ 2,181.00 18w
93	Rear bumper clips	1set	\$ 30w 70.00
94	Rear bumper lower garnish	1	\$ 249.00
95	Rear bumper RH reflector	1	\$ 45.00
96	Rear bumper LH reflector	1	\$ 45.00
97	Rear bumper RH upper retainer	1	\$ 23.00
98	Rear bumper LH upper retainer	1	\$ 23.00
99	Rear bumper RH lower retainer	1	\$ 44.00
100	Rear bumper LH lower retainer	1	\$ 44.00
101	Rear bumper reinforcement	1	\$ 945.00
102	Rear bumper RH side reverse sensor	1	\$ 244.00
103	Rear bumper RH centre reverse sensor	1	\$ 244.00
104	Rear bumper LH centre reverse sensor	1	\$ 244.00
105	Rear bumper LH side reverse sensor	1	\$ 244.00 nn
106	Rear bumper reverse sensor O-rings seal	4	\$ 48.00
107	Rear bumper reverse sensor wire harness	1	\$ 344.00 nn
108	LH taillamp assy	1	\$ 1,019.00
109	LH taillamp panel	1	\$ 185.00
110	RH taillamp assy	1	\$ 1,019.00
111	RH taillamp panel	1	\$ 185.00 nn
112	End panel assy	1	\$ 764.00
113	End panel inner garnish	1	\$ 178.00
114	End panel inner garnish clips	1set	\$ 40.00
115	Rear compartment panel top cover	1	\$ 711.00
116	Rear compartment panel	1	\$ 2,223.00 1705
117	Rear compartment panel insulator	1	\$ 121.00
118	Rear fender RH inner trim	1	\$ 787.00
119	Rear fender RH inner trim clips	1set	\$ 60.00
120	Rear fender RH splash shield	1	\$ 132.00
121	Rear fender RH splash shield clips	1set	\$ 30.00
122	Rear fender LH inner trim	1	\$ 787.00
123	Rear fender LH inner trim clips	1set	\$ 60.00
124	Rear fender LH splash shield		\$ 132.00
125	Rear fender LH splash shield clips		\$ 30.00
126	Exhaust silencer	1	\$ 1,083.00
127	Exhaust silencer heat shield	1	\$ 167.00
128	Exhaust silencer gasket	1	\$ 68.00
129	Rear battery cut off cable	1	\$ 558.00

\$ 68,003.00

Parts less 5% \$ 3,400.15

Total \$ 64,602.85

No.	Special Nett Items		Amount S\$
1	Radiator coolant	1	\$ 95.00 nu
2	Front grille "Quattro" sticker	1	\$ 125.00
3	Front number plate	1	\$ 80.00 45
4	End panel joint sealant	1	\$ 70.00
5	Rear compartment panel joint sealant	1	\$ 80.00

6	RH taillamp panel	1	\$	X	35.00
7	LH taillamp panel	1	\$	X	35.00
8	Rear number plate	1	\$	X	70.00

Total: \$ 590.00

No.	Labour and painting	Amount S\$
	(FRONT PORTION)	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 600 1,800.00
2	Spray painting on affected areas and panels	\$ 500 1,500.00
3	Check wiring and lighting system on affected areas	\$ 30 120.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 180.00
5	Remove and replace turbo intercooler and pipes to assist repair	\$ 50 220.00
6	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas	\$ 100 240.00
7	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant and check leakage	\$ 100 280.00
8	Refocus and adjust headlamps assy	\$ 30 50.00
	(REAR PORTION)	
9	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 900 2,200.00
10	Spray painting on affected areas and panels	\$ 900 1,800.00
11	Check wiring and lighting system on affected areas	\$ 30 120.00
12	Apply rust coating chemical on affected areas and panels	\$ 30 180.00
13	Remove and replace rear bumper reverse sensors and wire harness to assist repair	\$ 30 180.00
14	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 60 450.00
15	Remove and replace bootlid mechanism to new bootlid	\$ 60 180.00
16	Remove and replace exhaust silencer, gasket, mountings to assist repair	\$ 60 320.00
17	Mount vehicle on chassis alignment bench to repair chassis frames	\$ X 550.00

18	Remove and replace battery cut-off cable to assist repair	\$ X 280.00
19	Reset and diagnose control unit and fault code after repair	\$ 150 450.00
20	Remove and replace front and rear seat belts, buckles and control unit	\$ 100 550.00

Total: \$ 11,650.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 64,602.85

Special Nett: \$ 590.00

Labour: \$ 11,650.00

Total Amount: \$ 76,842.85

Tanflin 97495747 check repair unit.
 15/6/22 @ 1245
 Resurvey photo. To check part price
 To check consistency of accident
 1/5 Resurvey after repair
 Tanflin @ 11h45 to 12h00
 10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____