

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SGL 8683E
Vehicle Model : LEXUS RX200T
Accident Date : 10.06.2022
Original Reg Date : 18.07.2017

Date : 14.06.2022
Chassis : JTBAMCA002026228
TP Ins. **ERGO**

ESTIMATE

1	1 pc	Tailgate Top Garnish Cover	de		2066.50	1968
2	1 pc	Tailgate Emblem LEXUS	new		86.20	
3	1 pc	Tailgate Emblem RX200t	new		92.50	
4	1 pc	Tailgate Lamp RH	new		1396.80	1130
5	1 pc	Rear Bumper	de		1090.30	995
6	2 pcs	Rear Bumper Side Retainers	L4x RH 7 photo. ✓	159.00	318.00	
7	1 pc	Rear Bumper Side Bottom Retainers RH	7 photo ✓ de ✓		213.00	
8	1 set	Rear Bumper Clips	new ✓		40.00	
9	1 pc	Rear Bumper Reinforcement	X new		568.00	
10	1 pc	Rear Bumper Sponge	7 photo X new			
11	1 pc	End Panel	(R) photo ✓		973.00	RX
12	1 pc	Taillamp RH	new		1533.80	1046
13	1 set	Taillamp Clips	new ✓		25.00	
14	2 pcs	Rear Bumper Reverse Sensor (Original)	1 pc photo ✓	481.90	nw ✓ 963.80	481.90
15	2 pcs	Rear Bumper Reverse Sensor Holder	new ✓	42.00	84.00	

9,450.40 6320.60
Less 10% 945.04 5688.54
8,505.36

Labour charge

Panel Beating		800.00	500
Spray painting		1,000.00	700 700
Check Wiring		40.00	30
Anti rust		60.00	30
Remove and install reverse sensor		90.00	30
To reprogram & reset reverse sensor system		180.00	X new 1290

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphun 974957494 10,675.36
15/6/22 214m 1,067.54
9,607.82

1/3 Resurvey after repair
4 days
5688.54
1290

6978.54
1/3 5600
4 days