

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:**ECICS Limited (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	10/06/2022
Vehicle Reg. No.:	SMM6609H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A)	Vehicle Reg. Date:	09/07/2019
Vehicle Colour:	WHITE	Chassis No:	VF1RFA00962704561
Engine No:	K9KF649D059887		
Odometer:	246165 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8 ✓

*Not Authorised
Repair By paint
Ex @ 2000/-*

Present Location: MUNICH AUTOCARE PTE LTD (HQ)**COST OF CLAIMS****Amount**

Parts	36,580.15
Miscellaneous Items	189.00
Labour	4,170.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$)	40,939.15
- Excess (S\$)	2,000.00
(S\$)	38,939.15
+ GST 7.00% (S\$)	2,725.74
Nett Amount (S\$)	41,664.89

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2022)
Parts:	M1-MPV	RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Munich Autocare Pte Ltd/SMM6609H/14/06/2022 12:10	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	681009375R	*DASHBOARD ASSY	0.00	0.00	*3,674.90 F	✓
2	1	985254678R	*PASSENGER AIR BAG LH	0.00	0.00	*1,211.00 F	✓
3	1	985700230R	*STEERING WHEEL AIR BAG	0.00	0.00	*1,148.80 F	✓
4	1	255545857R	*ROTARY SWITCH	0.00	0.00	*429.90 F	✓
5	1	878163402R	*FRONT SEAT BELT TENSIONER RH	0.00	0.00	*210.90 F	?
6	1	878176089R	*FRONT SEAT BELT TENSIONER LH	0.00	0.00	*210.90 F	?
7	1	868854722R	*FRONT SEAT BELT LH	0.00	0.00	*743.40 F	✓
8	1	868841713R	*FRONT SEAT BELT RH	0.00	0.00	*743.40 F	✓
9	1	888414701R	*REAR SEAT BELT 2ND ROW LH	0.00	0.00	*948.20 F	✓
10	1	888403599R	*REAR SEAT BELT 2ND ROW RH	0.00	0.00	*948.20 F	✓
11	1	985109965R	*AIRBAG COMPUTER	0.00	0.00	*1,356.90 F	✓
12	1	651004703R	*FRONT BONNET	0.00	0.00	*1,348.00 F	✓
13	1	656016673R	*BONNET LOCK	0.00	0.00	*186.00 F	✓
14	1	656220664R	*BONNET LOCK HANDLE	0.00	0.00	*75.10 F	?
15	1	654000247R	*FRONT BONNET HINGE RH	0.00	0.00	*134.30 F	✓
16	1	658408772R	*FRONT BONNET INSULATOR	0.00	0.00	*295.20 F	✓
17	1	654704597R	*FRONT BONNET DAMPER RH	0.00	0.00	*112.20 F	✓
18	1	260101271R	*FRONT HEADLAMP RH	0.00	0.00	*892.50 F	✓
19	1	269257264R	*FRONT HEADLAMP BRACKET RH	0.00	0.00	*160.70 F	✓
20	1	631009903R	*FRONT FENDER RH	0.00	0.00	*645.60 F	✓
21	1	625124628R	*FRONT FENDER SIDE BRACKET RH	0.00	0.00	*226.40 F	✓
22	1	622907255R	*FRONT CENTRE BRACE BRACKET	0.00	0.00	*132.90 F	✓
23	1	620436650R	*FRONT FENDER INNER PANEL OUTER	0.00	0.00	*112.00 F	?
24	1	289107594R	*ENGINE WASHING TANK	0.00	0.00	*179.80 F	✓
25	1	638443888R	*FRONT WHEEL INNER SHIELD OUTER RH	0.00	0.00	*298.32 F	X
26	1	638423973R	*FRONT WHEEL SHIELD INNER RH	0.00	0.00	*298.32 F	X
27	1	620223972R	*FRONT BUMPER	0.00	0.00	*1,676.20 F	✓
28	1	625005785R	*FRONT SUPPORT PANEL	0.00	0.00	*1,214.30 F	✓
29	1	620358403R	*FRONT BUMPER SIDE BRACKET LH/RH	0.00	0.00	*330.24 F	?
30	1	261A24871R	*FRONT FOGLAMP MOULDING (CHROME)	0.00	0.00	*221.80 F	✓
31	1	261520089R	*FRONT FOGLAMP COVER	0.00	0.00	*221.80 F	✓
32	1	253A49995R	*FRONT PARKING SENSOR x 2	0.00	0.00	*2,228.80 F	4?
33	1	2843896148R	*FRONT BLIND SPOT SENSOR RH x2	0.00	0.00	*723.40 F	?
34	1	240704528R	*FRONT BUMPER SENSOR HARNESS WIRE	0.00	0.00	*183.10 F	?
35	1	623821034R	*FRONT RADIATOR GRILLE BLACK	0.00	0.00	*265.00 F	✓
36	1	623855072R	*FRONT RADIATOR GRILLE MOULDING (CHROME)	0.00	0.00	*329.80 F	✓
37	1	622561964R	*FRONT RADIATOR GRILLE	0.00	0.00	*473.80 F	✓
38	1	628905855R	*FRONT GRILLE EMBLEM	0.00	0.00	*167.00 F	?
39	1	620363937R	*FRONT RADIATOR TOP GARNISH	0.00	0.00	*458.40 F	✓
40	1	752106346R	*FRONT BUMPER REINFORCEMENT	0.00	0.00	*744.40 F	✓
41	1	620901789R	*FRONT BUMPER LOWER REINFORCEMENT GARNISH	0.00	0.00	*239.10 F	?
42	1	625300861R	*FRONT RADIATOR SUPPORT LOWER SUBFRAME	0.00	0.00	*707.20 F	?
43	1	622353354R	*FRONT ENGINE UNDER COVER	0.00	0.00	*617.80 F	X
44	1	7711428130	*COOLANT 5L	0.00	0.00	*24.20 F	✓
45	1	921004063R	*AIRCON CONDENSER	0.00	0.00	*930.00 F	?

	Part No.	Particulars	%Disc	%Depr	Amount
	1	144614EA1B *ENGINE INNER COOLER	0.00	0.00	*898.10 F ?
47	1	214105169R *RADIATOR	0.00	0.00	*725.40 F ?
48	1	214819674R *RADIATOR FAN COWLING ASSY	0.00	0.00	*937.20 F ?
49	1	628109433R *RADIATOR GRILLE INNER AIR DUCT	0.00	0.00	*165.30 F ?
50	1	215595656R *RADIATOR INNER AIR DUCT	0.00	0.00	*102.80 F ?
51	1	215586371R *INTERCOOLER AIR DUCT	0.00	0.00	*46.60 F ?
52	1	214F62853R *FRONT LOWER AIR INTAKE FLAP GUIDE	0.00	0.00	*597.40 F ?
53	1	622568767R *FRONT LOWER FLAP GUIDE INNER AIR DUCT	0.00	0.00	*251.60 F ?
54	1	214G39170R *BUMPER AIR INTAKE HARNESS FRT RH GS4	0.00	0.00	*65.80 F ?
55	1	217530327R *FRONT ENGINE WATER SPARE TANK PIPE SUPPORT	0.00	0.00	*106.30 F ?
56	1	668114330R *FRONT WIPER CENTER GARNISH	0.00	0.00	*878.00 F ?

F=Franchise part.

Sub Total (S\$) 33,254.68

+ Margin on L,N Items 10.00% (S\$) 3,325.47

Total Parts (S\$) 36,580.15

Munich Autocare Pte Ltd/SMM6609H/14/06/2022 12:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BUMPER SCREW	
2	1	FRONT WHEEL ARCH CLIPS	
3	1	TIMING BELT	
			42.00 ✓
			42.00 ✓
			105.00 7
Sub Total (S\$)			189.00

Estimates on Labour

No Particulars

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO WELADING REALIGN FRONT BUMPER, BONNET, FRONT FENDER RH, FRONT WINDS SUB FRAMER RH, SUPPORT PANEL AND ALL NECESSARY ETC	New	800.00
2	TO REMOVE & REPLACE RADIATOR FAN, HOSE AND AIR COND CONDENSER HOSE, FAN INCLUDING VECUUM AND TOP UP GAS	New	100.00 370.00
3	TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND TENSIONER LH & RH, BUCKLE LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH	New	250.00
4	TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND TENSIONER LH & RH, BUCKLE LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH	New	350.00
5	TO DIAGNOSTIC SETTING PASSENGER & DRIVER RESTRAINT SYSTEM AND RESETTNG OF ECU SYSTEM TO CLEAR FAULT CODE	New	250.00 380.00
6	TO CONDUCT 4 WHEEL ALIGMENT / TYRE BALANCING	New	120.00 x
7	TO RESPRAY FRONT ACCIDENT PORTION, BONNET, BUMPER, FENDER LH/RH, FRONT CHASSIS MEMBER RH AND NECESSARY ETC	New	1000.00 1,200.00
Gross Labour Cost (S\$)			4,170.00

Munich Autocare Pte Ltd/SMM6609H/14/06/2022 12:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: