

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMW747D
 Make & Model: Porsche Macan PDK
 Chassis number: WP1ZZZ95ZHLB00171

Date of survey:
 Name of surveyor:
 Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet <i>2455</i>	1	\$ 3,256.00
2	Bonnet emblem <i>296.70</i>	1	\$ 336.00
3	Bonnet inner heat insulator	1	\$ 438.00
4	Bonnet inner heat insulator clips	1set	\$ 80.00
5	Bonnet RH hinge	1	\$ 211.00
6	Bonnet LH hinge	1	\$ 211.00
7	Bonnet lock	1	\$ 378.00
8	Front bumper <i>1084.90</i>	1	\$ 1,621.00
9	Front bumper clips	1set	\$ 80.00
10	Front bumper RH side retainer	1	\$ 32.00
11	Front bumper LH side retainer	1	\$ 32.00
12	Front bumper grille	1	\$ 489.00
13	Front bumper inner air duct	1	\$ 203.00
14	Front bumper number plate garnish	1	\$ 339.00
15	Front bumper reinforcement	1	\$ 549.00
16	Front bumper inner sponge	1	\$ 89.00
17	Front bumper towing cover	1	\$ 72.00
18	Front bumper RH sensor	1	\$ 267.00
19	Front bumper LH sensor	1	\$ 267.00
20	Support panel	1	\$ 734.00
21	Support panel top garnish cover	1	\$ 252.00
22	Support panel top garnish cover clips	1set	\$ 50.00
23	RH headlamp assy <i>2673</i>	1	\$ 3,173.00
24	LH headlamp assy <i>2673</i>	1	\$ 3,173.00
25	Aircon condenser	1	\$ 1,893.00
25	Radiator assy	1	\$ 2,512.00

\$ 20,737.00
 Parts less 10% \$ 2,073.70
 Total \$ 18,663.30

9973.60
8976.24

No.	Special Nett Items	Qty	Amount S\$
1	Bonnet body wrap sticker	1	\$ 850.00
2	Front bumper body wrap sticker	1	\$ 700.00
3	Front number plate	1	\$ 70.00

ent - 400
car - 300
kn.
700

4	Radiator coolant	1	\$ M 120.00
Total:			\$ 1,740.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,500.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 70.00
4	Apply rust coating chemical on affected areas and panels	\$ 120.00
5	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas	\$ 250.00
6	Remove and replace radiator assy, hoses and pipes to assist repair. To refill coolant	\$ 250.00
7	Refocus and adjust headlamps assy	\$ 100.00
Total:		\$ 3,490.00

600
600
30
30
X nn
X nn
40
1300

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 18,663.30
 Special Nett: \$ 1,740.00
 Labour: \$ 3,490.00
Total Amount: \$ 23,893.30

Taufik 9949 5749 / 62563561
 'WP' 15/6/77R 1215pm

1/3 ready after repair
 taufik@lkkauto.com
 4 days.

To check consistency of accident
 # To check part prices.

8976.24
 700
 1300

10976.24
 458750
 4 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: