

bpr opr

DY

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : SML 4432T
Made : Honda
Model : Freed
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Front Bumper	1	\$ 1,160.70	\$ <i>dl</i> 1,160.70	986 ✓
2	Front Bumper Towing Cover	1	\$ 20.70	\$ <i>dl</i> 20.70	✓
3	Front Bumper Lower Lip	1	\$ 196.50	\$ <i>ewa</i> 196.50	✓
4	Front Bumper Lower Grille	1	\$ 346.70	\$ <i>dl</i> 346.70	233 ✓
5	Front Bumper Side Retainer RH	1	\$ 29.50	\$ <i>dl</i> 29.50	✓
6	Front Bumper Side Retainer LH	1	\$ 29.50	\$ <i>X nn</i> 29.50	
7	Front Bumper Reinforcement	1	\$ 347.60	\$ <i>bt</i> 347.60	✓
8	Front Bumper Engine Under Cover Centre	1	\$ 360.90	\$ <i>X nn</i> 360.90	
9	Front Fender RH	1	\$ 490.20	\$ <i>X nn</i> 490.20	
10	Front Fender LH	1	\$ 490.20	\$ <i>X nn</i> 490.20	
11	Front Fender Inner Shield RH	1	\$ 170.00	\$ <i>X nn</i> 170.00	
12	Front Fender Inner Shield LH	1	\$ 170.00	\$ <i>X nn</i> 170.00	
13	Front Grille Top	1	\$ 548.00	\$ <i>ewa</i> 548.00	✓
14	Front Grille Lower	1	\$ 159.00	\$ <i>X nn</i> 159.00	
15	Front Grille Emblem	1	\$ 89.00	\$ <i>ng</i> 89.00	✓
16	Front Grille Chrome Moulding	1	\$ 245.00	\$ <i>X nn</i> 245.00	
17	Front Headlamp Assembly RH (LED)	1	\$ 1,980.10	\$ <i>ewa</i> 1,980.10	1544 ✓
18	Front Headlamp Assembly LH (LED)	1	\$ 1,980.10	\$ <i>ewa</i> 1,980.10	1544 ✓
19	Front Headlamp Lower Bracket RH	1	\$ 56.50	\$ <i>ewa</i> 56.50	✓
20	Front Headlamp Lower Bracket LH	1	\$ 56.50	\$ <i>ewa</i> 56.50	✓
21	Front Bonnet	1	\$ 970.20	\$ <i>X nn</i> 970.20	
22	Front Bonnet Hinge RH	1	\$ 45.60	\$ <i>X nn</i> 45.60	
23	Front Bonnet Hinge LH	1	\$ 45.60	\$ <i>X nn</i> 45.60	
24	Front Bonnet Lock	1	\$ 163.70	\$ <i>X nn</i> 163.70	
25	Front Bonnet Lock Cable	1	\$ 75.60	\$ <i>X nn</i> 75.60	
26	Front Bonnet Inner Rubber (Front)	2	\$ 72.20	\$ <i>X nn</i> 144.40	
27	Front Bonnet Inner Rubber (Side)	2	\$ 68.70	\$ <i>X nn</i> 137.40	
28	Front Bonnet Insulator	1	\$ 149.20	\$ <i>X nn</i> 149.20	
29	Front Support Panel	1	\$ 896.00	\$ <i>X nn</i> 896.00	
30	Front Wire Harness	1	\$ 1,169.90	\$ <i>X nn</i> 1,169.90	
31	Air Guard	1	\$ 70.90	\$ <i>X nn</i> 70.90	
32	Radiator	1	\$ 1,502.20	\$ <i>X nn</i> 1,502.20	

33	Radiator Side Garnish RH	1	\$	75.80	\$	X nn	75.80
34	Radiator Side Garnish LH	1	\$	75.80	\$	X nn	75.80
35	Radiator Fan Motor	1	\$	398.80	\$	X nn	398.80
36	Radiator Fan Cowling	1	\$	165.10	\$	X nn	165.10
37	Radiator Fan Blade	1	\$	89.20	\$	X nn	89.20
38	Radiator Spare Tank	1	\$	74.70	\$	X nn	74.70
39	Aircon Condenser	1	\$	988.70	\$	X nn	988.70
40	Aircon Fan Blade	1	\$	84.80	\$	X nn	84.80
41	Aircon Fan Motor	1	\$	384.90	\$	X nn	384.90
42	Aircon Fan Cowling	1	\$	149.60	\$	X nn	149.60
43	Air Cleaner Resonator	1	\$	150.90	\$	X nn	150.90
44	Air Cleaner Resonator Duct	1	\$	95.10	\$	X nn	95.10
45	Air Duct	1	\$	64.50	\$	X nn	64.50
46	Air Flexible Duct	1	\$	142.50	\$	X nn	142.50
47	Front Temperature Sensor	1	\$	158.60	\$	X nn	158.60
48	Buzzer	1	\$	164.50	\$	X nn	164.50
49	Battery Tray	1	\$	42.20	\$	X nn	42.20
Parts Sub Total :							\$ 17,603.10
Discount 20%							\$ 3,520.62
PARTS TOTAL :							\$ 14,082.48

5651.30
-20%
5421.04

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Bumper Clips - Set	1	\$ 50.00	\$ 300.00 — 50.00
2	Front Grille Clips - Set	1	\$ 30.00	\$ 200.00 — 30.00
3	Front Fender Inner Shield Clips - Set	1	\$ 80.00	\$ X nn 80.00
4	Front Bonnet Insulator Clips - Set	1	\$ 30.00	\$ X nn 30.00
5	Radiator Coolant	1	\$ 50.00	\$ X nn 50.00
6	Front Bonnet Sealant	1	\$ 150.00	\$ X nn 150.00
7	Front Support Panel Sealant	1	\$ 150.00	\$ X nn 150.00
8	Front Fender Sealant	2	\$ 150.00	\$ X nn 300.00
9	Front Bumper Canards (1 Set) - Aftermarket	1	\$ 400.00	\$ X nn 400.00
10	Front Bumper Lower Spoiler - Aftermarket	1	\$ 600.00	\$ X nn 600.00
11	Front Bumper Sensor - Set	1	\$ 350.00	\$ X nn 350.00
SPECIAL NETT TOTAL :				\$ 2,190.00

50

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts	\$ 200 1,600.00
2	To Spray Paint Affected Areas	\$ 300 1,600.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Remove & Refix Aircon Condenser & Top Up Gas	\$ X 150.00
5	To Remove & Refix Radiator & Conduct Pressure Test	\$ X 150.00
6	To Remove & Refix Front Bumper Sensor	\$ 30 120.00
7	To apply anti rust on affected parts	\$ X 120.00
8	To Conduct Water Leak Test	\$ X 100.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
660		LABOUR TOTAL : \$ 4,420.00

Temples 9749 7747
 WP 15/6/270 1240
 L/S Repair after repair
 temples (Mhants) on
 To check consistency of accident -
 To check part price
 03 days

PARTS TOTAL : \$ 14,082.48
 SPECIAL NETT TOTAL : \$ 2,190.00
 LABOUR TOTAL : \$ 4,420.00
 GRAND TOTAL : \$ 20,692.48

6131.04

L/S - 4904.83
= 4900