

bee ORR

DY

**Bifrost Auto Pte Ltd**

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875  
Tel: 93290237 Email: claims\_rar@bifrostauto.com

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Date of ReSurvey: \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : SML 4432T  
Made : Honda  
Model : Freed  
Chassis No : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Front Bumper	1	\$ 1,160.70	\$ <del>dl</del> 1,160.70	986 ✓
2	Front Bumper Towing Cover	1	\$ 20.70	\$ <del>dl</del> 20.70	✓
3	Front Bumper Lower Lip	1	\$ 196.50	\$ <del>ca</del> 196.50	✓
4	Front Bumper Lower Grille	1	\$ 346.70	\$ <del>dl</del> 346.70	233 ✓
5	Front Bumper Side Retainer RH	1	\$ 29.50	\$ <del>dl</del> 29.50	✓
6	Front Bumper Side Retainer LH	1	\$ 29.50	\$ X nn 29.50	
7	Front Bumper Reinforcement	1	\$ 347.60	\$ <del>bt</del> 347.60	✓
8	Front Bumper Engine Under Cover Centre	1	\$ 360.90	\$ X nn 360.90	
9	Front Fender RH	1	\$ 490.20	\$ X nn 490.20	
10	Front Fender LH	1	\$ 490.20	\$ X nn 490.20	
11	Front Fender Inner Shield RH	1	\$ 170.00	\$ X nn 170.00	
12	Front Fender Inner Shield LH	1	\$ 170.00	\$ X nn 170.00	
13	Front Grille Top	1	\$ 548.00	\$ <del>ca</del> 548.00	✓
14	Front Grille Lower	1	\$ 159.00	\$ X nn 159.00	
15	Front Grille Emblem	1	\$ 89.00	\$ <del>ng</del> 89.00	✓
16	Front Grille Chrome Moulding	1	\$ 245.00	\$ X nn 245.00	
17	Front Headlamp Assembly RH ( LED )	1	\$ 1,980.10	\$ <del>pa</del> 1,980.10	1544 ✓
18	Front Headlamp Assembly LH ( LED )	1	\$ 1,980.10	\$ <del>ca</del> 1,980.10	1544 ✓
19	Front Headlamp Lower Bracket RH	1	\$ 56.50	\$ <del>ca</del> 56.50	✓
20	Front Headlamp Lower Bracket LH	1	\$ 56.50	\$ <del>ca</del> 56.50	✓
21	Front Bonnet	1	\$ 970.20	\$ X nn 970.20	
22	Front Bonnet Hinge RH	1	\$ 45.60	\$ X nn 45.60	
23	Front Bonnet Hinge LH	1	\$ 45.60	\$ X nn 45.60	
24	Front Bonnet Lock	1	\$ 163.70	\$ X nn 163.70	
25	Front Bonnet Lock Cable	1	\$ 75.60	\$ X nn 75.60	
26	Front Bonnet Inner Rubber ( Front )	2	\$ 72.20	\$ X nn 144.40	
27	Front Bonnet Inner Rubber ( Side )	2	\$ 68.70	\$ X nn 137.40	
28	Front Bonnet Insulator	1	\$ 149.20	\$ X nn 149.20	
29	Front Support Panel	1	\$ 896.00	\$ X nn 896.00	
30	Front Wire Harness	1	\$ 1,169.90	\$ X nn 1,169.90	
31	Air Guard	1	\$ 70.90	\$ X nn 70.90	
32	Radiator	1	\$ 1,502.20	\$ X nn 1,502.20	

33	Radiator Side Garnish RH	1	\$	75.80	\$ X nn	75.80
34	Radiator Side Garnish LH	1	\$	75.80	\$ X nn	75.80
35	Radiator Fan Motor	1	\$	398.80	\$ X nn	398.80
36	Radiator Fan Cowling	1	\$	165.10	\$ X nn	165.10
37	Radiator Fan Blade	1	\$	89.20	\$ X nn	89.20
38	Radiator Spare Tank	1	\$	74.70	\$ X nn	74.70
39	Aircon Condenser	1	\$	988.70	\$ X nn	988.70
40	Aircon Fan Blade	1	\$	84.80	\$ X nn	84.80
41	Aircon Fan Motor	1	\$	384.90	\$ X nn	384.90
42	Aircon Fan Cowling	1	\$	149.60	\$ X nn	149.60
43	Air Cleaner Resonator	1	\$	150.90	\$ X nn	150.90
44	Air Cleaner Resonator Duct	1	\$	95.10	\$ X nn	95.10
45	Air Duct	1	\$	64.50	\$ X nn	64.50
46	Air Flexible Duct	1	\$	142.50	\$ X nn	142.50
47	Front Temperature Sensor	1	\$	158.60	\$ X nn	158.60
48	Buzzer	1	\$	164.50	\$ X nn	164.50
49	Battery Tray	1	\$	42.20	\$ X nn	42.20
			Parts Sub Total :		\$	17,603.10
			20% Discount		\$	3,520.62
			PARTS TOTAL :		\$	14,082.48
			5651.30			
			-20%			
			5421.04			

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Bumper Clips - Set	1	\$ 50.00	\$ 50.00
2	Front Grille Clips - Set	1	\$ 30.00	\$ 30.00
3	Front Fender Inner Shield Clips - Set	1	\$ 80.00	\$ 80.00
4	Front Bonnet Insulator Clips - Set	1	\$ 30.00	\$ 30.00
5	Radiator Coolant	1	\$ 50.00	\$ 50.00
6	Front Bonnet Sealant	1	\$ 150.00	\$ 150.00
7	Front Support Panel Sealant	1	\$ 150.00	\$ 150.00
8	Front Fender Sealant	2	\$ 150.00	\$ 300.00
9	Front Bumper Canards ( 1 Set ) - Aftermarket	1	\$ 400.00	\$ 400.00
10	Front Bumper Lower Spoiler - Aftermarket	1	\$ 600.00	\$ 600.00
11	Front Bumper Sensor - Set	1	\$ 350.00	\$ 350.00
SPECIAL NETT TOTAL :				\$ 2,190.00

Nos.	LABOUR	S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 200	1,600.00
2	To Spray Paint Affected Areas	\$ 300	1,600.00
3	Wiring & Bulb Check	\$ 30	100.00
4	To Remove & Refix Aircon Condenser & Top Up Gas	\$ X	150.00
5	To Remove & Refix Radiator & Conduct Pressure Test	\$ X	150.00
6	To Remove & Refix Front Bumper Sensor	\$ 30	120.00
7	To apply anti rust on affected parts	\$ X	120.00
8	To Conduct Water Leak Test	\$ X	100.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
660		<b>LABOUR TOTAL :</b>	<b>\$ 4,420.00</b>

Taufik 9749 7777  
 WP 15/6/22 @ 1240  
 L/S Repair after repair -  
 temp. @ 1/1/2020  
 To check consistency of accident -  
 To check part price  
 03 days

PARTS TOTAL : \$ 14,082.48  
 SPECIAL NETT TOTAL : \$ 2,190.00  
 LABOUR TOTAL : \$ 4,420.00  
**GRAND TOTAL : \$ 20,692.48**

6131.04

L/S - 4904.83  
= 4900

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: