

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22005642/RQY3M4**Date:** 26/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00079762200		
Claimant Vehicle No :	SNF965T	Insured Vehicle No :	SNE5699J		
Date of Loss:	08/06/2022	Nature of Claim:	TP	Claim No:	SNM22D204060/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNF965T</b>	Engine No:	L15Z1005594
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RV31004757
Reg. Date:	29/04/2022 (Man. Year: 2022)	Odometer:	2550 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,100.56	2,050.32	1,050.24	33.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	810.00	980.00	54.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,890.56</b>	<b>2,860.32</b>	<b>2,030.24</b>	<b>41.51</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	342.34	200.22	142.12	41.51
<b>Nett Amount (\$\$)</b>	<b>5,232.90</b>	<b>3,060.54</b>	<b>2,172.36</b>	<b>41.51</b>

**INSPECTION**

Date of Assignment:	23/07/2022		
Date Inspected:	27/06/2022	Inspected At:	160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722 REPAIRER: VIN'S MOTOR PTE LTD
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF965T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,332.50 FL	*1,332.50 FL
2	1		*FRONT RH DOOR OUTER MOULDING	Not Necessary	75.30 FL	*- FL
3	1		*FRONT RH FENDER	Repair	639.10 FL	*- FL
4	1		*FRONT RH WHEEL ARCH GARNISH	Scratched	173.30 FL	*173.30 FL
5	1		*FRONT RH SPORT RIM (R16)	Scratched	1,057.10 FL	*1,057.10 FL
6	1		*FRONT RH KNUCKLE BEARING	Not Necessary	598.40 FL	*- FL
					Sub Total (S\$)	3,875.70 2,562.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	775.14 512.58
					Total Parts (S\$)	3,100.56 2,050.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WHEEL ALIGNMENT	New	150.00	60.00
2	TO REMOVE AND REPLACE BEARING	New	180.00	0.00
3	TO REPAIR DAMAGES	New	580.00	350.00
4	TO SPRAY PAINTING	New	880.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,790.00</b>	<b>810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >