

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605
Hp: 91839633 E-mail: vianong@gmail.com

ESTIMATE REPORT

Vehicle Number : SLQ1200B
 Make And Model : Jaguar XJ
 Date of Accident : 10 Jun 2022

S/No	Parts	QTY	Unit Price	List Price
1	Rear bumper	1		\$ 2,563.10
2	Rear bumper chrome trim	1		\$ 531.70
3	Rear bumper bracket mounting outer LH & RH	2	\$ 75.60	\$ 151.20
4	Rear bumper bracket mounting inner LH & RH	2	\$ 71.40	\$ 142.80
5	Rear bumper lower cover	1		\$ 460.00
6	Rear bumper sponge LH & RH	2	\$ 230.00	\$ 460.00
7	Rear bumper reinforcement	1		\$ 1,590.00
8	Rear bumper reverse sensor	2	\$ 182.39	\$ 364.78
9	Rear bumper sensor holder	4	\$ 30.45	\$ 121.80
10	Rear taillamp LH & RH	2	\$ 1,238.00	\$ 2,476.00
11	Bootlid	1		\$ 3,179.50
12	Bootlid 'LOGO' emblem	1		\$ 81.10
13	Bootlid 'JAGUAR' emblem	1		\$ 88.80
14	Bootlid 'XJ' emblem	1		\$ 68.80
15	Bootlid lock	1		\$ 549.00
16	Bootlid weatherstrip	1		\$ 256.00
17	Rear end panel	1		\$ 1,959.00
18	Rear end panel top garnish	1		\$ 146.21
19	Reverse camera	1		\$ 891.30
20	Rear number plate lamp LH & RH	2	\$ 132.00	\$ 264.00
				\$ 17,628.51
Less 15%				\$ 2,644.28
Total				\$ 14,984.23

Special Nett Item				
1	Rear number plate	1	\$ 40	50.00
2	Rear bumper rivet & clips	1 set	\$ 40	100.00
3	Rear bootlid inner trimboard clips	1 set	\$ 40	100.00
Total				\$ 250.00

120

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for rear portion.

To spray paint on affected areas for rear portion.

To remove/replace/reinstall rear bootlid components.

To remove/replace/reinstall rear panel upholstery & trim.

To apply anti-rust on affected areas.

To remove/replace/reinstall reverse sensors.

To remove/replace/reinstall reverse camera.

To check wiring for rear portion.

To perform system diagnostic & reset ECU.

\$	1,200.00	400
\$	1,000.00	400
\$	150.00	50
\$	200.00	?
\$	100.00	30
\$	100.00	30
\$	150.00	80
\$	100.00	50
\$	400.00	X
Total	\$ 3,400.00	
Grand Total :	\$ 18,634.23	1040

= 10,385.65

L/S-8308-52

= 8300

ster CLKK/
15/6/22, 12.00p
8322 8813

M AL
L/S
M AL Y
4 L/S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: