

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 23/06/2022

User ID : PohSuan

Section A - Accident Details

Registration Number	SHB423H
Case Reference Number	TAX/06/22/2038
Registration Date	8/9/2014
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YONG CHEE YOONG
Type of Accident	Head to Rear
Accident Date and Time	9/6/2022 8:10 PM
Accident Reported Date and Time	10/6/2022 2:28 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115262
Special Instruction to ARC, if any	TP/ REAR PORTION
Prepared Date and Time	10/6/2022 3:16 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$1,448.39	\$287.76
Total Other Cost	\$380.00	\$30.00
TOTAL COST	\$3,242.39	\$717.76
Lump Sum Total	\$3,250.00	\$700.00 (L/S)
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / AIG
ARC / Surveyor Sign Off Date	13/06/2022 8:40 AM	10/06/2022 4:19 PM
Signature		
Remarks		resurvey after repair photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2206-0244	Invoice Number	
Quotation Date	22.06.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	\$30.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
Total					\$2,303.60		\$359.70		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

359.70

-20%

287.76

L/S \$700/-

+ 200.00

+ 230.00

717.76