V	ASSIGNMENT
rom: Date:	Veh No: SHB423H. Yr Regn: 2014 1 Sep. Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
slimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi / Prime Mover /
DO FTP IWS ITP RES I OD RES I EVA I INV I MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Toyota Prins c.c 1798
at Workshop m/s	Colour Maroon A/C: Insured / Std / NI / NA
of	Sp.Reading 73203/ T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: 5T PUN 3646057 48535.
Claims No.	Gen. Cond: Good/ Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inother / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nji / S/Pam / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 7 ,
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY /-FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO or Seilun.
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Bal. 6 mm
Est Repairs: days Res.: Yes or No	D.O.A. D.O.I. 10/6/27
Lum Sum: % 3 Val.: Yes or No	Survey held at SMRT WL
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: II	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
	
	1
,	
Date/Time, File Pass to? Proli Report	D. 01D. 1
. Tell. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) 🛆	dd Fee:: Site Insp (\$)s+Rssi
. ————	
	: Interview (\$) Photos
Reput Format : Lump Sum / I.B.J.: (7):	: Interview (\$) Photos : Tech. Invs (\$) Others



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 10/06/2022
User ID : angbangkien

	Section A - Accider	nt Details				
Registration Number	SHB423H					
Case Reference Number	TAX/06/22/2038					
Registration Date	8/9/2014	27.40				
Company Type		144				
Make	Strides Taxi Pte Ltd					
fodel	PRIUS					
lame of Driver	YONG CHEE YOONG	A 200				
ype of Accident	Head to Rear					
Accident Date and Time		*				
Accident Reported Date and Time	9/6/2022 8:10 PM	- Manager				
s Surveyor Required?	10/6/2022 2:28 PM	State.				
Survey by	Yes					
/ehicle is Towed Back?	N-					
owed Back Date and Time	No	and Address com-				
Replacement Vehicle issued?	N					
ob Card Number	No	And a grade of				
pecial Instruction to ARC, if any	24115262					
repared Date and Time	TP/ REAR PORTION					
Chassis Number	10/6/2022 3:16 PM					
Mileage						
Vork Shop						
·						
Repair Completion Date and Time						
	Section B - Summary of Re	pair Estimates				
ummary of Repair Estimates	The state of the s	(A)				
	Quotation from ARC	Adjusted by Surveyor, if applicable				
otal Labour Cost	\$676.00	\$200.00				
otal Spray Cost	\$738.00	\$200.00				

	Par isveniences			
Quotation from ARC	Adjusted by Surveyor, if applicable			
\$676.00	\$200.00			
\$738.00	\$200.00			
\$1,448.39	\$287.76			
\$380.00	\$30.00			
\$3,242.39	\$717.76			
\$2,900.00	\$700.00			
4.0	2.0			
Boon Chew Tay	Taufikh			
10/06/2022 3:32 PM	10/06/2022 4:19 PM			
-	Ten			
	resurvey after repair photo			
	\$676.00 \$738.00 \$1,448.39 \$380.00 \$3,242.39 \$2,900.00 4.0 Boon Chew Tay			

Section C - Quotation and Accident Invoice Details						
luotation Number	Invoice Number					
luotation Date	Invoice Date					
voice Amount	Prepared Date					



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 10/06/2022

User ID

: angbangkien

art 1 - Labo	101	SAMPLE OF THE REAL PROPERTY.	Sect	ion D - Det	ails of Repair I	Estimates	(4)			
ait i - Labo	ur Works							9.1		
ob Scope			Quotation from AR				Adjusted by Surveyor, if applicable			
O REPAIR REAR PORTION			\$676.00				\$200.00			
otal Labour				\$676.00				\$200.00		
art 2 - Spra	v Painting & F	Panel Beating Rel	ated Works	- 50 per 18 mm			- er samen	allering and a second		
and opid	y running a r	arier beating item	ated Works					Adjusted by Surveyo	or. If applicat	ole
ob Scope			Quotation from ARC				Adjusted by Garreyer, in Spr			
ORESPRAY	REAR BUMPE	R	The control of the co	\$378.00	Control of the contro			\$200.00		
O RESPRAY	REAR PANEL		And the state of t	\$180.00		elle:		\$0.00		
O RESPRAY	BUMPER BEAL	М		\$180.00				\$0.00		
otal Spray Pa	ainting & Panel	Beating		\$738.00			, 100 m	\$200.00	Consultation of the State of th	
art 3 - Other	r Costs - Acci	dent and Acciden	t Repair Related Expen	se						
ob Scope			Quotation f	rom ARC	A STATE OF THE STA		Adjusted by Surveyo	or, if applicat	010	
O WASH AND	VACUUM			\$60.00			of the second	\$0.00		to Neille E
O APPLY RUST-PROOFING ON AFFECTED AREA				\$100.00				\$0.00		
O TEST AND REFIX REVERSE SENSOR SYSTEM				\$120.00				\$30.00		
O REPLACE SUNDRY PARTS				\$100.00				\$0.00		
otal Other Costs				\$380.00				\$30.00		
last A - Spare	e Parts / Mate	rial lleane								
art Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor A	pproved
1000				1.00	\$458.60	25.00	\$343.95	Replace	Replace	ريان
		52159-47905	BUMPER REAR	10.00	\$2.10	25.00	\$15.75	Replace	Replace	Wes
		90467-07211 52023-12240	BUMPER CLIPS BUMPER	0.00	\$205.70	0.00	\$0.00	Replace	Check	0
		52023-12240	REINFORCEMENT REAR	0.00					Oh II	•
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	?
	- Italia	52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	7
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given	XNM
	- Marie -		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	1
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	Xny
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X~~
A SALLOW		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	xnn
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	Xu
otal					\$2,303.60		\$359.70			
dded Spare	Parts / Materi	al Usage After Su	rveyor Signed off		The state of the s			tanga jigar da sa		99.85
				Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor C	heck
art Number	Portion	Stock Number	Part Name	Quantity	Figt Lines &	2.3count (78)	a. 1 1108 (\$)	LICO OHECK	Curveyor C	on

Taylor 9749549
WY 10/6/2184pm
US Mary after report
22 days

toughth @ libratoron

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2age 2 of 2

otal