

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/07/2022
User ID PohSuan
Section A - Accident Details

Registration Number	SHC4500L
Case Reference Number	TAX/06/22/2034
Registration Date	4/9/2014
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA CHENG HWA
Type of Accident	Head to Rear
Accident Date and Time	8/6/2022 8:00 AM
Accident Reported Date and Time	9/6/2022 11:17 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115252
Special Instruction to ARC, if any	FRONT PORTION DAMAGED
Prepared Date and Time	9/6/2022 5:17 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$5,508.25	\$672.55
Total Other Cost	\$380.00	\$0.00
TOTAL COST	\$7,302.25	\$1,072.55
Lump Sum Total	\$7,300.00	\$1,050.00 (L/S)
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / AIG
ARC / Surveyor Sign Off Date	16/06/2022 9:52 AM	15/06/2022 2:41 PM
Signature		
Remarks	Total number of repair days = 2 days. SUP = 0 day.	resurvey after repair photo

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 05/07/2022

User ID : PohSuan

		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given	X
		81521-47050	LENS & BODY,FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X
		75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace	✓
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X
		53113 - 47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	X
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given	X
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given	X
		81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given	X
Total					\$8,069.11		\$548.26			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace
Total					389.90		292.43		

	840.69	
	-20%	
	672.55	L/S \$1,050/-
+	200.00	
+	200.00	
	1,072.55	

