



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM22005652/Dpa3q2 Date: 19/10/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFC 6333M	Veh. Inspected	PZ 8C
	Policy No.	P2442435	Coverage (\$)	0.00
	Claim No.	S2M0440S	Excess (\$)	0.00
	Assign From		Assign Date	14/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE HIGH ROOF	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFST22P800037021	Colour	WHITE
	Odometer	156654 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	BRIDGESTONE	5 mm
	L/H Front Tyre	195 R15C	BRIDGESTONE	5 mm
	R/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm
	L/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/06/2022	Inspection Date	15/06/2022
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	