



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

14.6.22 10:30AM

Date : 10/06/2022

Attn: The Motor Claims Department

WITHOUT PREJUDICE

Your Insured veh no : SGX 799 Y

AIG ASIA PACIFIC INSURANCE PTE LTD.

(By Email Only)

78 Shenton Way

07-16 Chartis Building

Singapore 079120

Xiao Tong

Dear Sir / Madam

Estimated Cost of repair for Vehicle No. Lexus SGX327Z And SKX799Y On 05/06/2022 @ 13:15pm.

ToSupply :-

1pc	Front Bumper	<i>Rys</i>		<u>SSS</u>	968.20	x
10pcs	Front Bumper Clips	<i>Joan</i>	10pcs X \$12.00		120.00	+
2pcs	Front Side Retainer		2pcs X \$58.90		117.80	+
1pc	Sport Rim	<i>Rys</i>			1,000.00	<i>Local Price (150)</i>
1pc	Front Fender	<i>Rys</i>			1,314.70	x
					<hr/>	
					3,520.70	
				Less 25%	<hr/>	
					-880.18	
					<hr/>	
					2,640.53	

To dismanlte & replace damage parts,panel beat where necessary

To putty,apply primer & spray paint on the affecte portion.

To adjust Wheel Alignments

To check wiring functions.

580.00 ~~200~~
600.00 ~~400~~
120.00 +
100.00 x
4,040.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Adrian G
P/P 13/06/22.
03 Days*

*total: 750
(P/P)*