

EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722
Tel: 64560226 Fax: 64584500
GST Reg. No: 201016308K

ESTIMATE

Date : 20th June 2022

Ms **Ong Hwee Yan**
Blk 712 Hougang Ave 2 #04-273
Singapore 530712

Veh No : **SLP 8158A**
Make/Model : **Lexus UX250H**
Chassis No : JTHY65BH002094563
Date of Acc : 13.06.22
TP Veh No : GBF 5221R

S/No	Qty	Description	Unit Price	Amount
<u>Materials</u>				
1	1 pc	Bonnet		\$ 2,603.90 X
2	1 pc	Frt Fender RH		\$ 1,285.90 X
3	1 pc	Headlamp RH 3934		\$ 4,131.60 ✓
4	1 pc	Frt Side Bumper RH 345		\$ 434.80 ✓
5	1 pc	Frt Bumper Side Retainer RH		\$ 83.00 ✓
6	1pc	Frt Bumper Bracket RH		\$ 249.60 X
				\$ 8,788.80
			Less 10% :	\$ 878.88
				\$ 7,909.92
				\$ 55.00 ✓
7	1 set	Frt Bumper Clips		
			Parts Total :	\$ 7,964.92
<u>Labour</u>				
1	To remove & rearrange electrical wirings, check lightings			\$ 80.00 201
2	To remove, repair & replace damaged bodyparts and where consistent to the accident.			\$ 800.00 401
3	Putty and respray painting on affected portions.			\$ 800.00 601
4	To remove & refit PDC sensor.			\$ 80.00 501
5	Rust proofing on affected portions.			\$ 100.00 X
			Labour Total :	\$ 1,860.00
			Total Parts & Labour :	\$ 9,824.92


for EM Solution Pte Ltd

Not Authored
Pursuing by painting
4 days
11pm @ 4000h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: