

来發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No .. .: EST0029583 Tan Ghee Lin Jeremy

Page 1 of 1 Your ref. TP-SMG 9478E AGI Job No. 72764 Our ref . Payment Date

Vehicle No . . : SGQ 7640J Vehicle Model : Honda Civic Accident on ..: 11/6/2022

Not Nothain Penny Athe Pany 8950/2 3day,

Quantity Unit	Description	Unit price Disc. pct.	Amount
100000000000000000000000000000000000000	Labour & Misc:		
1.00	To remove + refix rear door outer handle LH; to knock dents on rear fender LH + rear door	200.00	200.00
	and Octor		7501
1.00	To spray paint (including rear sport rim LH and rear bumper)	800.00	800.00

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approvel from Insurance Comp

5\$

Acknowledged by Repairer Signature:

Sub-Total GST 7.00% Total

1,000.00 70.00 1.070.00

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁棒罐。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Accident report SC0S226B0002

Page 1 of 22