

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22005662/DVY3M4**Date:** 02/08/2022**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000820488-01  
**Claimant Vehicle No :** FBE3688X **Insured Vehicle No :** SLU1297B  
 Date of Loss: 06/06/2022 Nature of Claim: TP Claim No: 202222005145KC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBE3688X**  
 Make & Model: HONDA CB400, 399cc Engine No: NC42E1006591  
 Reg. Date: 11/03/2010 (Man. Year: 2008) Chassis No: JH2NC42938K010044  
 Colour: Grey Odometer: 0 km  
 Engine Capacity: 399 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 120/60 R17 Rear Tyre Size: 160/60 R17  
 Front Left Side: Pirelli 2 mm Rear Left Side: Pirelli 2 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,380.00	2,044.50	2,335.50	53.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	410.00	690.00	62.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,480.00</b>	<b>2,454.50</b>	<b>3,025.50</b>	<b>55.21</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,950.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,480.00</b>	<b>1,950.00</b>	<b>3,530.00</b>	<b>64.42</b>

**INSPECTION**

Date of Assignment: 14/06/2022  
 Date Inspected: 15/06/2022 Inspected At: SG 98 MOTOR PTE LTD (HQ)  
 BLK 4001 ANG MO KIO INDUSTRIAL PARK 1  
 #01-21  
 SINGAPORE 569622  
 Estimated Period of Repair: 3.0 days

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 02 Aug 2022)	
<b>Parts:</b>	N/A	HONDA CB400 399cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBE3688X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	150.00 FL	*- FL
2	1		*SET FORK TUBE	Serviceable	950.00 FL	*- FL
3	1		*RADIATOR	Bent	800.00 FL	*350.00 FL
4	1		*RADIATOR GUARD	Bent	150.00 FL	*80.00 FL
5	1		*SET CRASH BAR	Dented	380.00 FL	*380.00 FL
6	1		*SET BALANCER	Not fitted	220.00 FL	*- FL
7	1		*BRAKE LEVER	Cut	95.00 FL	*95.00 FL
8	1		*YOSHIMURA PIPE	Dented	1,350.00 FL	*1,350.00 FL
9	1		*FRONT RIM	Repair	350.00 FL	*- FL
10	1		*TAIL PANEL	Not Necessary	280.00 FL	*- FL
11	1		*SET FORK OIL SEAL	Not Necessary	125.00 FL	*- FL
12	1		*FRONT NUMBER PLATE	Bent	15.00 F	*15.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,865.00</b>	<b>2,270.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	485.00	225.50
<b>Total Parts (\$\$)</b>	<b>4,380.00</b>	<b>2,044.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PIPE INSPECTION FEE & LEGAL CERT	New	150.00	60.00
2	TOWING FEE	New	40.00	0.00
3	REMOVE & REPLACE NECESSARY PARTS, FORK TUBE, RIM, ETC	New	380.00	200.00
4	PUTTY & RESPRAY PAINT TO AFFECTED BODY	New	280.00	0.00
5	REPLACE FRONT RIM LABOUR & RESPRAY	New	250.00	150.00
			<b>Gross Labour Cost (\$)</b>	<b>410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >