

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

AHMAD LUTFI MAULA SHAMSUDIN
 BLK 661C JURONG WEST ST 64 #14-436
 SINGAPORE 643661

TP Chiam

Hui Rong

Contact : 87526875, 97345102

TAX INVOICE

Repair Code : CLM17257

Date in : 13/06/2022

Vehicle Num. : SKT482G

Model : KIA CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR

Chassis/Eng# : KNAFW411MA5121071/G4FC9H289821

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Damaged</i>	1	948.00	✓ 948.00
REAR BOOTLID 'LOGO' EMBLEM <i>new</i>	1	43.00	✓ 43.00
REAR BOOTLID HINGES L/R <i>new</i>	2	62.00	✗ 124.00
REAR BOOTLID INNER TRIM BOARD <i>new</i>	1	132.00	✗ 132.00
REAR BOOTLID MECHANISM LOCK <i>Damaged</i>	1	105.00	✓ 105.00
REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>	2	30.00	✗ 60.00
REAR BOOTLID OUTER HANDLE <i>new</i>	1	206.00	✗ 206.00
REAR BOOTLID WEATHER STRIP <i>cut</i>	1	90.00	✓ 90.00
REAR BUMPER <i>Damaged</i>	1	548.00	✓ 548.00
REAR BUMPER LOWER BRACKET <i>new</i>	3	28.00	✓ 84.00
REAR BUMPER LOWER LID <i>Damaged</i>	1	101.00	✓ 101.00
REAR BUMPER REINFORCEMENT <i>Cracked</i>	1	302.00	✓ 302.00
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Best LH</i>	2	92.00	92 184.00
REAR BUMPER REVERSE SENSOR <i>Damaged & piers.</i>	4	184.00	368 736.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	20.00	✓ 80.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	1	194.00	✓ 194.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	21.00	✓ 42.00
REAR BUMPER SPONGE <i>Cracked</i>	1	141.00	✓ 141.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

AHMAD LUTFI MAULA SHAMSUDIN
 BLK 661C JURONG WEST ST 64 #14-436
 SINGAPORE 643661

Contact : 87526875, 97345102

TAX INVOICE

Repair Code : CLM17257
 Date in : 13/06/2022
 Vehicle Num. : SKT482G
 Model : KIA CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
 Chassis/Eng# : KNAFW411MA5121071/G4FC9H289821

REAR END PANEL	<i>Dented</i>	1	262.00	<i>✓</i>	262.00
REAR END PANEL INNER TOP GARNISH	<i>Del d</i>	1	52.00	<i>✓</i>	52.00
REAR EXHAUST RUBBER MOUNTING	<i>2 piece</i>	2	30.00	<i>+</i>	60.00
REAR EXHAUST SILENCER BOX	<i>4063</i>	1	696.00	<i>+</i>	696.00
REAR FENDER INNER TRIM BOARD L/R	<i>torn</i>	2	137.00	<i>✓</i>	274.00
REAR FLOOR PANEL TOP BOARD COVER	<i>Del d</i>	1	139.00	<i>✓</i>	139.00
REAR TAILLAMP L/R	<i>Crashed</i>	2	196.00	<i>✓</i>	392.00
Subtotal before discount					5,995.00
Percentage discount 10%					599.50
Sub-total 1					5,395.50
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>Not seen</i>	1	50.00	<i>+</i>	50.00
REAR BOOTLID NUMBER PLATE	<i>Not seen</i>	1	25.00	<i>+</i>	25.00
REAR BOOTLID NUMBER PLATE HOLDER	<i>Not seen</i>	1	50.00	<i>+</i>	50.00
REAR BOOTLID OUTER HANDLE CLIPS - SET	<i>Not seen</i>	1	40.00	<i>10-40.00</i>	
REAR BOOTLID TOP SPOILER	<i>Not seen</i>	1	600.00	<i>+</i>	600.00
REAR BUMPER CLIPS - SET	<i>Not seen</i>	1	50.00	<i>30-50.00</i>	
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>Not seen</i>	1	40.00	<i>10-40.00</i>	
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	<i>Not seen</i>	2	50.00	<i>60-100.00</i>	

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

AHMAD LUTFI MAULA SHAMSUDIN
 BLK 661C JURONG WEST ST 64 #14-436
 SINGAPORE 643661

Contact : 87526875, 97345102

TAX INVOICE

Repair Code : CLM17257
 Date in : 13/06/2022
 Vehicle Num. : SKT482G
 Model : KIA CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
 Chassis/Eng# : KNAFW411MA5121071/G4FC9H289821

REAR TAILLAMP CLIPS L/R - SET	<i>New</i>	2	130	25.00	<i>20</i> 50.00
Subtotal before discount					1,005.00
Percentage discount 0%					0.00
Sub-total 2					1,005.00
Parts-total					6,400.50

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	60.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>60</i>	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>800</i>	1,100.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	<i>x</i>	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>1840</i>	1,000.00
To apply anti-rust chemical on repaired and replaced panel.	<i>60</i>	120.00
To transfer rear bootlid mechanism lock outer handle reflector	<i>60</i>	80.00
Labour Total		2,560.00
Parts & Labour Total		8,960.50

Adrian Lij
L/S 16/06/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is a computer-generated document which requires no signature.***

06 Days
total: 5626.70
L/S: H.SKV