# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From:

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

LKK Auto Consultants Pte Ltd

Singapore 408933

JANICE KOH 17 Jun 2022 Attn: Date:

## **Preliminary Advice**

Vehicle No : SLM1701T Accident Date : 11/06/2022

Make : HYUNDAI AE IONIQ HEV Policy No. : SPM71000000515

Assignment Date : 14/06/2022 **Excess** : S\$0.00 Date of Inspection : 15/6/2022 Est. Duration of Repair : 5

: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM) Inspection At

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,966.67
Revised Amount	:S\$	3,984.11
Check Items (Estimated)	:S\$	2,696.00
Total	:S\$	6,680.11

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old value :5\$	New for Old	d Value	:S\$
------------------------	-------------	---------	------

Pre-Accident Value 72,000.00 :S\$ COE / PARF Rebate 28,668.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 43,332.00

#### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments: Part by part repair as there is no 2nd parts available.

> Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.