

Co. & G.S.T. Reg no. 201605297G Workshop: 23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933 Email: automim.claim@gmail.com Tel: 9119 8371 Website: www.aimgarage.com.sg

ESTIMATE

Our Ref: AC2022042/OD

Vehicle number:SLM1701T

Vehicle Made & Model: HYUNDAI AE IQNIQ HEV 1.6

Qty	<u>List Items</u>		Amount \$
1 1 pc	Front bumper Pistarted		\$230.00
2 12 pc	Front bumper clip @ \$2.00 xlv		\$24.00
3 1 pc	Front bumper lower lip ?		\$150.00
4 1 pc	Front bumper lower grille De Co		\$55.00
5 1 pc	n/s Front fog lamp Miss		\$330.00
6 1 pc	n/s Front fog lamp trim De		\$65.00
7 1 pc	Front bumper foam culd		\$60.00
8 1 pc	Front bumper beam ?		\$420.00
9 1 pc	Front bumper lower beam culcd		\$65.00
10 2 ps	Front bumper side retainer @ \$19.60 1-14 Pm d		\$39.20-19.60
11 1 pc	Front bumper top garnish		\$35.00
12 1 pc	Front bumper top garnish rubber seal He ~		\$20.00 -
13 1 pc	Front grille Cruc &		\$550.00
14 1 pc	Front grille base ?		\$350.00 .
15 1 pc	Radar sensor Mr.		\$450.00 イ
16 2 ps	Front actuator H ~		\$230.00 ~
17 1 pc	Parking sensor wire harness 7		\$145.00 3
18 2 ps	Headlamp@\$550 LH Smushed		\$1,100.00 550
19 2 ps	Headlamp garnish ?		\$65.00
20 1 pc	n/s Front fender Develo		\$220.00 ~
21 1 pc	n/s Front fender inner cowling De Ld		\$80.50
22 8 ps	n/s Front fender inner cowling clips @ \$2.00		\$16.00
23 1 pc	n/s Front fender BLUE DRIVE lettering the		\$25.00
24 1 pc	Support guard ?		\$350.00
25 1 pc	Support guard top garnish ?		\$35.00 3
26 1 pc	n/s Air guide ?		\$85.00 ?
27 1 pc	Main fuse box The m		\$950.00 +
28 1 pc	Engine under plastic?		\$125.00
		Sub-total	\$6,269.70
		Cost +10%	\$626.97
		Total List	\$6,896.67
	Special Nett Item		
1 set	Front parking sensor plem		\$450.00
	1 1		

Labour charges

Labour charges to remove and refix of parts and panel beating.	\$900.00 600 \$80.00 30
To check electrical lighting.	
Re-route wire harness	\$120.00
To install of front parking sensor.	\$80.00 50
Top up aircon gas	\$80.00 7
Top up radiator coolant \$80	\$80.00 ?
Scan fault code and reprogramm radar sensor	\$480.00 ?
Spray painting.	\$800.00 600
	\$2,620.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

\$ 9,966.67

Adria Cip
Not Atlansed
15/06/22.
05 laps.

Style (No 2nd parts
available)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: