

SONG YI AUTO PARTS PTE LTD

7 Veerasamy Road #01-119 Singapore 200637
3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

TAX CASH SALE

REG NO: 200922096G
GST NO: 200922096G

No: CSA22-103862
Date: 22/06/2022 12:50
Account No: CS
Sales Person: Colin
Order By:
Vehicle No: SLM1701T
P/O No: HU028867

Delivery To: AUTOMOBILE INTEGRATED MANAGEMENT
AKI BUKIT AVE 4 #04-01 - VICOM INSPECTION CENTRE

Page 1 of 1

Part No	Description	Location	Qty	Price	Amount
501-G2040 MBI	HEAD LAMP ASSY-LH	WH	1	550.00	550.00
520-G2000	SPONGE-FRT BUMPER	WH	1	60.00	60.00
571-G2000	STIFFNER-FRT BUMPER LWR	WH	1	65.00	65.00
513-G2000	BRACKET-FRT BUMPER SIDE LH	WH	1	19.60	19.60
563-G2050	MOULDING-FRT BUMPER SIDE LH	WH	1	65.00	65.00
101-G2000	PANEL-RAD SUPPORT @@@	WH	1	350.00	350.00
61-G2000	GUARD-RAD GRILLE UPR		1	38.00	38.00
720-F2000 RB4	SENSOR-PARKING (FRT) @@@	WH	1	185.00	185.00
MP	AIR GUIDE		1	85.00	85.00
321-G2000	BLUE DRIVE EMBLEM LH	WH	1	25.00	25.00
391-G2010	WIRING HARNESS-FWS EXT		1	220.00	220.00

Sub Total: 1,662.60

Add GST @7%: 116.38

Grand Total: 1,778.98

Handwritten signature

Sold are not returnable

Issued by



7 松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Seerasamy Road #01-119 Singapore 200637
00 Fax: 6297 3839 Email: songyi@singnet.com.sg

TAX CASH SALE

REG NO: 200922086G
GST NO: 200922086G

No: CSA22-103914
Date: 25/06/2022 12:15
Account No: CS
Sales Person: Colin
Order By:
Vehicle No: SLM1701T
P/O No: HU028867

Delivery To: AUTOMOBILE INTEGRATED MANAGEMENT
1 BUKIT AVE 4 #04-01 - VICOM INSPECTION CENTRE

Page 1 of 1

No	Description	Location	Qty	Price	Amount
C1000	BUZZER-PIEZO	WH	1	70.00	70.00
G2000	BRACKET-FRT BUMPER SIDE LH	A	1	15.00	15.00

Sub Total: 85.00

Add GST @7%: 5.95

Grand Total: 90.95

are not returnable

Issued by



松義汽車機件私人有限公司

SONG YI AUTO PARTS PTE LTD

Veerasamy Road #01-119 Singapore 200637
 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

TAX CASH SALE

REG NO: 200922086G
 GST NO: 200922086G

No: CSA22-103899
 Date: 24/06/2022 14:29
 Account No: CS
 Sales Person: Colin
 Order By:
 Vehicle No: SLM1701T
 P/O No: HU028867

Delivery To: AUTOMOBILE INTEGRATED MANAGEMENT
 AKI BUKIT AVE 4 #04-01 - VICOM INSPECTION CENTRE

Page 1 of 1

Item No	Description	Location	Qty	Price	Amount
MP	FRONT GRILE MLDG		1	70.00	70.00
Sub Total:					70.00
Add GST @7%:					4.90
Grand Total:					74.90

sold are not returnable

Issued by



SPRINTER AUTOMOBILE

Retail: Blk 32 Sin Ming Drive #01-319/#01-333 Singapore 575706
Tel: 6456 4243 Fax: 6457 3411

Tel: 6456 4226, 6456 4243 Fax: 6457 3411

Co. Reg. No.: 52885038E GST Reg. No.: M90365425N

Wholesales & Retail, New or Used Spare Parts

出入口各式新舊汽車零件

TAX INVOICE
TAX CASH SALES

1917

Carl 37367171

No: 183662

SLM1701T Vicom 04-01

Date, 22/6/22

貨名 PARTICULARS	單價 Unit Price	銀額 Amount
New 10N10 Front bumper		\$ 280
" " bumper lower grille		\$ 150
" " Fog lamp	Ln	\$ 330
" " Grille		\$ 550
" " Head lamp garnish		\$ 70
" " fender	Ln	\$ 230
" " Engine cover		\$ 120
" " Lower Grille mounting		\$ 70
pay now 96357574		
Ng Yong Hwa		

概不退换。
are not Returnable.

Subtotal

7% GST

TOTAL

ion will be processed as a MEPS payment if the amount is more than S\$200,000.

Name" field is for reference only. The payee's bank will process your request solely based on the payee's account number.

the status of your transaction to make sure that it has been successfully processed.

hat the Recurring function for FAST Payment is not working. We apologise for the inconvenience caused and are working to resume the