

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 20 Mar 2023

Preliminary Advice

Insured Vehicle No	: SJH9513S	Accident Date	: 09/06/2022
TP Vehicle No	: SHC553K	Assignment Date	: 15/06/2022
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 18
Date of Inspection	: 15/06/2022		
Inspection At	: BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	69,751.30
Revised Amount	:S\$	39,808.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	39,808.48

Lump Sum Repair	:S\$	25,000.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Book Value	:S\$	49,992.75
COE / PARF Rebate	:S\$	24,208.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,784.75

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.