

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

Reprint: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000
 ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES2290647
 Date: 28 Jun 2022
 Policy No: Z21VC05007917
 Veh Reg No: GBJ6917P
 Make/Model: TOYOTA TOYOTA
 DYNA 150
 Chassis No: JTFAT35Y90K213648
 Engine No: 1KD2859810
 Reg. Date: 18/07/2019

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 13/06/2022
 TP Veh Reg No: SM62C

Estimate Repair Cost to Vehicle No :GBJ6917P

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR TAILGATE	1,185.00	1 PC	1,185.00	✓
2 REAR TAILGATE STICKER- TOYOTA	202.50	1 PC	202.50	✓
3 TAILGATE STICKER - DYNA	67.20	1 PC	67.20	✓
4 REAR NUMBER PLATE PANEL	124.80	1 PC	124.80	✓
5 REAR EXHAUST PIPE	656.00	1 PC	656.00	✓
6 REAR EXHAUST PIPE HOLDER	85.70	1 PC	85.70	✓
7 REAR SPARE TYRE TRAY HOLDER LOCK	260.90	1 PC	260.90	✓
8 REAR TAILGATE HANDLE LH	90.50	1 PC	90.50	✓
9 REAR TAILGATE LOCK LH	63.80	1 PC	63.80	✓
10 TAILLAMP LH	202.00	1 PC	202.00	✓
11 TAILLAMP PANEL LH	79.00	1 PC	79.00	✓
			3,017.40	
	Less 25%		754.35	2,263.05
Special Net				
12 REAR LH CORNAL STOPPER	18.00	1 PC	18.00	✓
13 REAR NO. PLATE	20.00	1 PC	20.00	✓
14 REAR STEP TRAY	120.00	1 PC	120.00	✓
			158.00	158.00
Labour				
15 TO REMOVE AND REFIX RR TAILGATE ASSY, LOCK AND HANDLE, RR NO. PLATE PANEL, LH TAILLAMP; KNOCK AND REPAIR RR END PANEL, LH SIDE ANGLE PANEL, REPAIR AND REPLACE RR SPARE TYRE BRACKET AND RE-ALIGN REAR TRUCK IN POSITION AND OTHER TO SAME	650.00	1 LA	650.00	600
16 TO PUTTY AND RESPRAY ON TAILGATE, REAR LH SIDE LOWER MEMBER, REAR LOWER MEMBER, REAR NO. PLATE PANEL	550.00	1 LA	550.00	500
			1,200.00	1,200.00

1,200.00
 Reprint: 1

Total S\$ 3,621.05
 Add GST @ 7% 253.47
 Total Amount Payable S\$ 3,874.52

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature

Date: