

ASS. REQ. BY:

REF: ICS/CS/ICS22005673/Kqy3Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. DMCF2200093HSum Insured: _____ Excess: 2k

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$88k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

\$30,359.00

15/06/22 @ 4.36pm revert to Crystabelle Tan via Merimen.

16/06/22 @ 5.43pm Crystabelle Tan informed Offer LS \$6200 exclude check items via Merimen.

17/06/22 @ 10.41am Informed wksp C/A on LS \$6200 exclude check items & ex: \$2000 by email.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

) S - RS. \$

) Fines

) Others

) TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) _____

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	11/06/2022
Vehicle Reg. No.:	SMH6127H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	RENAULT SCENIC IV, 1.5 D L DCI SR	Vehicle Reg. Date:	28/01/2019
	EU6 (A)		
Vehicle Colour:	Brown		
Engine No:	K9KF649D059509	Chassis No:	VF1RFA00861978016
Odometer:	217560 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 days		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

*Not Authorised
Payment B4 repair
Ex R2000*

COST OF CLAIMS

	Amount
Parts	17,147.14
Miscellaneous Items	94.00
Labour	2,480.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	19,721.14
- Excess (S\$)	2,000.00
(S\$)	17,721.14
+ GST 7.00% (S\$)	1,240.48
Nett Amount (S\$)	18,961.62

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2022)
 Parts: M1-MPV RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Munich Autocare Pte Ltd/SMH6127H/14/06/2022 10:45
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	651004703R-237103738R	*FRONT BONNET	0.00	0.00	*1,348.00 F	✓
2	1	R658479275R	*BONNET TOP BACK TRIM GS4	0.00	0.00	*540.40 F	X
3	1	654000247R	*BONNET HINGE RH	0.00	0.00	*134.30 F	?
4	1	654013594R	*BONNET HINGE LH	0.00	0.00	*134.30 F	✓
5	1	654704597R	*BONNET DAMPER LH	0.00	0.00	*112.20 F	X
6	1	654704597R	*BONNET DAMPER RH	0.00	0.00	*112.20 F	X
7	1	658408772R	*BONNET INSULATOR	0.00	0.00	*295.20 F	X
8	1	656016673R	*BONNET LOCK	0.00	0.00	*186.00 F	?
9	1	656220664R	*BONNET LOCK HANDLE	0.00	0.00	*75.10 F	X
10	1	623821034R	*RADIATOR GRILLE BLACK	0.00	0.00	*265.00 F	✓
11	1	623855072R	*RADIATOR GRILLE CHROME MOULDING	0.00	0.00	*346.80 F	✓
12	1	622561964R	*RADIATOR GRILLE	0.00	0.00	*473.80 F	✓
13	1	620363937R	*FRONT RADIATOR GRILLE TOP GARNISH	0.00	0.00	*458.40 F	✓
14	1	628905855R	*FRONT EMBLEM	0.00	0.00	*167.00 F	✓
15	1	253A49995R	*FRONT PARKING SENSOR x2	0.00	0.00	*1,114.40 F	?
16	1	240704528R	*FRONT BUMPER SENSOR HARNESS WIRE	0.00	0.00	*183.10 F	?
17	1	R144614EA1B	*ENGINE INNER COOLER	0.00	0.00	*898.10 F	?
18	1	215586371R	*INTERCOOLER AIR DUCT	0.00	0.00	*46.60 F	?
19	1	620223972R	*FRONT BUMPER	0.00	0.00	*1,676.20 F	✓
20	1	620347326R	*FRONT BUMPER SIDE BRACKET RH	0.00	0.00	*154.60 F	X
21	1	620358403R	*FRONT BUMPER SIDE BRACKET LH	0.00	0.00	*154.60 F	X
22	1	622540901R	*FRONT BUMPER LOWER LIP	0.00	0.00	*431.01 F	✓
23	1	622552918R	*FRONT BUMPER SIDE INNER BRACKET LH	0.00	0.00	*167.70 F	?
24	1	622541628R	*FRONT BUMPER SIDE INNER BRACKET RH	0.00	0.00	*167.70 F	?
25	1	625005785R	*FRONT SUPPORT PANEL	0.00	0.00	*1,214.30 F	?
26	1	R752106346R	*FRONT BUMPER REINFORCEMENT	0.00	0.00	*744.40 F	?
27	1	622907255R	*FRONT CENTRE BRACE BRACKET	0.00	0.00	*132.90 F	?
28	1	620901789R620906523R	*FRONT BUMPER REINFORCEMENT LOWER GARNISH	0.00	0.00	*239.10 F	?
29	1	622353354R	*FRONT BUMPER UNDER DEFLECTOR	0.00	0.00	*617.80 F	?
30	1	269257264R	*FRONT HEADLAMP BRACKET RH	0.00	0.00	*160.70 F	?
31	1	269257264R	*FRONT HEADLAMP BRACKET LH	0.00	0.00	*160.70 F	X
32	1	261520089R	*FOGLAMP COVER LH	0.00	0.00	*261.40 F	✓
33	1	261520089R	*FOGLAMP COVER RH	0.00	0.00	*261.40 F	?
34	1	261A24871R	*FOGLAMP CHROME MOULDING	0.00	0.00	*261.40 F	?
35	1	261500097R	*FOGLAMP RH	0.00	0.00	*106.50 F	X
36	1	260602165R	*HEADLAMP LH	0.00	0.00	*892.50 F	X
37	1	260101271R	*HEADLAMP RH	0.00	0.00	*892.50 F	✓

F=Franchise part.

Sub Total (S\$) 15,588.31
 + Margin on L,N Items 10.00% (S\$) 1,558.83

Total Parts (S\$) 17,147.14

Munich Autocare Pte Ltd/SMH6127H/14/06/2022 10:45. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIP	49.00
2	1	FRONT LICENSE PLATE WITH CASING	45.00
Sub Total (\$\$)			94.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO PANAL BEATING , REALIGN DISMANTLE FRONT BUMPER , SUPPORT PANEL , BONNET, AND ALL NECESSARY ETC	New	1,200.00
2	TO CHECK ELECTRICAL WIRING SYSTEM OF FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLAMP LH/RH & FOGLAMP LH/RH	New	80.00
3	TO DISMAITE & RENEW FRONT PARKING SENSOR	New	80.00
4	TO APPLY TUFF COASTING AND SPRAY ANTI RUST PROOFING REAR PORTION	New	120.00
5	TO PUTTY & RESPRAY PAINTING FRONT BUMPER, SUPPORT PANAL, BONNET ,AND ALL NECESSARY ETC	New	1,000.00
Gross Labour Cost (\$\$)			2,480.00

Munich Autocare Pte Ltd/SMH6127H/14/06/2022 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	055D
Vehicle No.:	SMH6127H
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jun 2022
Vehicle Make:	RENAULT
Vehicle Model:	GRAND SCENIC IV 1.5 DCI AT EU6
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	K9KF649D059509
Chassis No.:	VF1RFA00861978016
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$25,440.00
Original Registration Date:	28 Jan 2019
First Registration Date:	28 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$17,616.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2029
PARF Rebate Amount:	\$13,212.00
COE Expiry Date:	27 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,920.00
COE Rebate Amount:	\$17,147.00
Total Rebate Amount:	\$30,359.00

The information contained herein is correct as at 15 Jun 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/06/2022 17:37 (SGT)
Date of Accident	11/06/2022 11:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	T-JUNCTION BEFORE TRAFFIC LIGHT ALONG NEW UPPER CHANGI RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMH6127H

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	+65-86881311

VEHICLE PARTICULARS

Manufacturer	Renault
Model	Scenic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1500


INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	MCF22A00000100
Cover Note Number	-

DRIVER

Name of Driver	MOHAMED ZAHRAIN BIN MOHAMED ZAINAL ABIDIN
----------------	---

SKETCH PLAN



VEHICLE A - SMH 6127H
VEHICLE B - GIBB 5199T
VEHICLE C - SNA 7114M

New Upper Chang RD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police Report x/b T/20220611/2036

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

