

ASS. REC. BY:

REF:

1CS/ 22 005673/kg

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH 6127H

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault

(A) Wagon

C.C.

1981

Colour

M. Grey

Sp. Reading

217560

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VFIRFA 00861978016

Gen. Cond: Good Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/55R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Turador

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

B30359-u

417/1 Lp 8680d Caber (Red, 12.921.14, 66%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trlp:

2

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

6800

TOTAL

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	11/06/2022
Vehicle Reg. No.:	SMH6127H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	RENAULT SCENIC IV, 1.5 D L DCI SR	Vehicle Reg. Date:	28/01/2019
	EU6 (A)		
Vehicle Colour:	Brown		
Engine No:	K9KF649D059509	Chassis No:	VF1RFA00861978016
Odometer:	217560 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 days		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

11/2000 @ 68000 Not Authorized
Recovery B4 paint
Ex @ 20000

COST OF CLAIMS

	Amount
Parts	17,147.14
Miscellaneous Items	94.00
Labour	2,480.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	19,721.14
- Excess (S\$)	2,000.00
(S\$)	17,721.14
+ GST 7.00% (S\$)	1,240.48
Nett Amount (S\$)	18,961.62

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2022)
 Parts: M1-MPV RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Munich Autocare Pte Ltd/SMH6127H/14/06/2022 10:45
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	651004703R-237103738R	*FRONT BONNET 1348	R	0.00	0.00	*1,348.00 F ✓
2	1	R658479275R	*BONNET TOP BACK TRIM GS4	Sm	0.00	0.00	*540.40 F X
3	1	654000247R	*BONNET HINGE RH		0.00	0.00	*134.30 F X
4	1	654013594R	*BONNET HINGE LH	R	0.00	0.00	*134.30 F X
5	1	654704597R	*BONNET DAMPER LH	Sm	0.00	0.00	*112.20 F X
6	1	654704597R	*BONNET DAMPER RH	Sm	0.00	0.00	*112.20 F X
7	1	658408772R	*BONNET INSULATOR	Sm	0.00	0.00	*295.20 F X
8	1	656016673R	*BONNET LOCK	R	0.00	0.00	*186.00 F X
9	1	656220664R	*BONNET LOCK HANDLE	R	0.00	0.00	*75.10 F X
10	1	623821034R	*RADIATOR GRILLE BLACK	CM	0.00	0.00	*265.00 F ✓
11	1	623855072R	*RADIATOR GRILLE CHROME MOULDING	CM	0.00	0.00	*346.80 F ✓
12	1	622561964R	*RADIATOR GRILLE	CM	0.00	0.00	*473.80 F ✓
13	1	620363937R	*FRONT RADIATOR GRILLE TOP GARNISH	Sm	0.00	0.00	*458.40 F ✓
14	1	628905855R	*FRONT EMBLEM	Sm	0.00	0.00	*167.00 F ✓
15	1	253A49995R	*FRONT PARKING SENSOR x2	Sm	0.00	0.00	*1,114.40 F X
16	1	240704528R	*FRONT BUMPER SENSOR HARNESS WIRE	Sm	0.00	0.00	*183.10 F X
17	1	R144614EA1B	*ENGINE INNER COOLER ✓	R	0.00	0.00	*898.10 F ✓
18	1	215586371R	*INTERCOOLER AIR DUCT ✓	CM	0.00	0.00	*46.60 F ✓
19	1	620223972R	*FRONT BUMPER 1461.70	Sm/CM	0.00	0.00	*1,676.20 F ✓
20	1	620347326R	*FRONT BUMPER SIDE BRACKET RH	Sm	0.00	0.00	*154.60 F X
21	1	620358403R	*FRONT BUMPER SIDE BRACKET LH	Sm	0.00	0.00	*154.60 F X
22	1	622540901R	*FRONT BUMPER LOWER LIP	CM	0.00	0.00	*431.01 F ✓
23	1	622552918R	*FRONT BUMPER SIDE INNER BRACKET LH	R	0.00	0.00	*167.70 F X
24	1	622541628R	*FRONT BUMPER SIDE INNER BRACKET RH	R	0.00	0.00	*167.70 F X
25	1	625005785R	*FRONT SUPPORT PANEL ✓ 1214.00	CM	0.00	0.00	*1,214.30 F ✓
26	1	R752106346R	*FRONT BUMPER REINFORCEMENT	R	0.00	0.00	*744.40 F X
27	1	622907255R	*FRONT CENTRE BRACE BRACKET	Sm	0.00	0.00	*132.90 F X
28	1	620901789R620906523R	*FRONT BUMPER REINFORCEMENT LOWER GARNISH	CM	0.00	0.00	*239.10 F ✓
29	1	622353354R	*FRONT BUMPER UNDER DEFLECTOR	Sm	0.00	0.00	*617.80 F X
30	1	269257264R	*FRONT HEADLAMP BRACKET RH	Sm	0.00	0.00	*160.70 F X
31	1	269257264R	*FRONT HEADLAMP BRACKET LH	Sm	0.00	0.00	*160.70 F X
32	1	261520089R	*FOGLAMP COVER LH	Sm	0.00	0.00	*261.40 F X
33	1	261520089R	*FOGLAMP COVER RH	Sm	0.00	0.00	*261.40 F X
34	1	261A24871R	*FOGLAMP CHROME MOULDING	Sm	0.00	0.00	*261.40 F X
35	1	261500097R	*FOGLAMP RH	Sm	0.00	0.00	*106.50 F X
36	1	260602165R	*HEADLAMP LH	Sm	0.00	0.00	*892.50 F X
37	1	260101271R	*HEADLAMP RH	Sm/CM	0.00	0.00	*892.50 F ✓

F=Franchise part.

Sub Total (S\$) 15,588.31
 + Margin on L,N Items 10.00% (S\$) 1,558.83
 Total Parts (S\$) 17,147.14

Munich Autocare Pte Ltd/SMH6127H/14/06/2022 10:45. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BUMPER CLIP	49.00
2	1	FRONT LICENSE PLATE WITH CASING	45.00
Sub Total (S\$)			94.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PANAL BEATING , REALIGN DISMANTLE FRONT BUMPER , SUPPORT PANEL , BONNET, AND ALL NECESSARY ETC	New	1,200.00
2	TO CHECK ELECTRICAL WIRING SYSTEM OF FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLAMP LH/RH & FOGLAMP LH/RH	New	80.00
3	TO DISMAITE & RENEW FRONT PARKING SENSOR	New	80.00
4	TO APPLY TUFF COASTING AND SPRAY ANTI RUST PROOFING REAR PORTION	New	120.00
5	TO PUTTY & RESPRAY PAINTING FRONT BUMPER, SUPPORT PANAL, BONNET ,AND ALL NECESSARY ETC	New	1,000.00
Gross Labour Cost (S\$)			2,480.00

Munich Autocare Pte Ltd/SMH6127H/14/06/2022 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >