

ASS. REC. BY:

REF:

TL / 22005674/Ku

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

874K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PUS 92810

Yr Regn:

10, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy CTR

c.c

1797

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

321787

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZYX10

2071335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

28/5/22

D.O.I.

15/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1:30pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/6 11:20 83400 Cdn

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

) \$ + RS. \$

) Fuel

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

# Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
Tel : 64817221

Fax : 64816131

H L Car Rental Pte Ltd  
Blk 5034 #01-337  
Ang Mo Kio Industrial Pk 2  
Singapore 569537

Vehicle No : SLS 9281 D  
Make : Toyota C-HR  
Year : 2017

*NOT Notified  
L1 Rep @ 5400k  
Resurvey After Paint  
6 days*

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

## Estimate Cost Of Repair

|       |                                   |        |            |   |
|-------|-----------------------------------|--------|------------|---|
| 1 pc  | Rear tail-gate assy               |        | \$1,320.60 | ✓ |
| 2 pcs | Rear tail-gate reflector          |        | \$1,244.48 | ✓ |
| 1 pc  | Rear tail-gate outer garnish      | 745.60 | \$891.20   | ✓ |
| 1 pc  | Rear tail-gate inner lock         | 389.40 | \$452.70   | ✓ |
| 1 pc  | Rear tail-gate emblem - Hybrid    |        | \$48.90    | ✓ |
| 1 pc  | Rear tail-gate emblem - C-HR      |        | \$45.80    | ✓ |
| 1 pc  | Rear tail-gate emblem             |        | \$62.30    | ✓ |
| 1 pc  | Rear boot rubber                  | 93.95  | \$187.90   | ✓ |
| 1 pc  | Rear bumper                       | 543.10 | \$875.60   | ✓ |
| 1 pc  | Rear bumper reinforcement         | 382    | \$483.20   | ✓ |
| 2 pcs | Rear bumper reflector garnish     |        | \$96.10    | ✓ |
| 2 pcs | Rear bumper reflector             |        | \$65.10    | ✓ |
| 1 pc  | Rear bumper centre garnish        |        | \$75.20    | ✓ |
| 1 pc  | Rear lower bumper                 |        | \$487.10   | ✓ |
| 1 pc  | Rear bumper tow cover             |        | \$45.80    | ✓ |
| 2 pcs | Rear bumper side retainer         |        | \$75.10    | ✓ |
| 1 pc  | Rear antenna                      |        | \$175.10   | ✓ |
| 1 pc  | Rear inner lock sensor            |        | \$187.60   | ✓ |
| 2 pcs | Rear fender arch garnish          |        | \$165.20   | ✓ |
| 1 pc  | Rear end panel                    | 725.70 | \$725.70   | ✓ |
| 1 pc  | Rear end panel inner garnish      | 347.40 | \$402.10   | ✓ |
| 1 pc  | Rear spare tool compartment       |        | \$320.10   | ✓ |
| 2 pcs | Rear fender inner trim board      | 499.50 | \$550.10   | ✓ |
| 1 pc  | Rear exhaust silencer             |        | \$855.90   | ✓ |
| 1 pc  | Rear exhaust silencer heat shield |        | \$155.20   | ✓ |

Less 25 % \$2,736.42  
balance c/f \$8,209.26

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLS 9281 D

balance b/f \$8,209.26

S Nett

15 pcs

1 pc Rear bumper clip  
1 pc Rear reverse sensor  
1 pc Rear windscreen sealant  
Rear no plate

\$2.00 *Mc* \$30.00 ✓  
*Short* \$200.00 ✓  
*Mc* \$40.00 ✓  
*Sn* \$35.00 X  
\$305.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 *Good*

To putty & spray paint on accident affected portion

\$1,200.00 *Good*

Check and reconnect wiring

\$40.00 *20%*

To anit- rust proofing

\$100.00 *60%*

Remove/refit rear windscreen

\$120.00 ✓

Total \$11,174.26