

ASS. REG. BY:

REF:

CTZ / 220056751kv

Kenneth

ASSENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s: NGS

of _____

Insured: SKM 2282R

Policy No. DMPCSNW00066042200

Claims No. SNM22D204125/C02/LEEPG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 01/25 Person Contacted: _____ Vehicle: IN / OUT

No: STV 2659C Yr Reg: 01, 10

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

1516 Corato Fortis 1591

M. Corry A/C: Insured / Std / NI / NA

Registration: 213247 T/Radio: Insured / Std / NI / NA

Chassis No: KNAFW411MA5175007

Cond: Good / Fair / Poor / Burnt

Engine: In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Wheels: Nil / S/Rim / STD / RIM or

Tire Size: F: B.S

R: 225/65R17

STUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOKO or

Front: 2 mm Rear: 3 mm FRONT

Left: 2 mm Right: 4 mm B.S

MA: 10/6/22 D.O.I: 15/6/2022

Damage held at _____

Damage: Frt / Rear / OIS / NIS / UIC / Rooftop or

NIS FR body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 GIA will email over.

17/6/22 Kenneth informed LS \$1950 (Red 2077.44, 51%)

Date/Time, File Pass to?

: Prell. Report

Days to Repair: 4

: Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

Survey Fee:

1) 17/6/22-typist

Add Fee: Site Insp (\$)

Transportation:

Interview (\$)

\$ - R.S. \$

Tech Invs (\$)

Fuels

Overknd (\$)

Others

Report Format: Merimen

Lump Sum / I.B.I: (\$1950)

03, 18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047
 Tel: 9695 5547 Fax: 6481 5727 e-mail: evelynnstrading@gmail.com
 Reg No: 201812604N

15/06/22

China Taiping Ins (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909
 Attn: Motor Claims Dept

*Not withold
 L/Ly &
 Repair After Paint
 4 days*

RE: Accident On 10/06/22@07:28Hrs Pm
 Ang Mo Kio Ave 3 Towards Hougang Ave 2
 Involving SJV2659C & SKM2282R
 Claims against SKM2282R (China Taiping)

We submit herewith our direct claim estimate quotation as follow:-
 Replacement parts - KIA CERATO

1	Frt Fender LH			\$	407.50	X
1	Frt Door LH			\$	1,017.00	✓
14	Clips, Fender Lining	S.Nett	~	\$	70.00	X
1	Rocker panel			\$	474.50	✓
				\$	1,969.00	
				Less 20%	\$	(236.06)

To remove frt damaged parts with all necessary components/
 attachments, repair/reshape dented body panel

\$ 800.00 *600*

Replace/reposition damaged parts, refit align into Refix all
 necessary components/attachment.

Transfer Door mechanism

\$ 150.00 *60*

Spray Painting - Frt Fender, Frt Door & Rocker Panel

\$ 800.00 *600*

\$ 4,027.44

Any other parts which necessitate repair or renewal will incur additional charged.
 Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
 EVELYN NG

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: