#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI22005681/TNY3E2

**Date:** 06/07/2022

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MN000207

Claimant Vehicle SHA2331G Insured Vehicle No: SLR8056A

Date of Loss: 13/06/2022 Nature of Claim: TP Claim No: M2203059

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHA2331G

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A) Engine No: 2ZRR927988

Reg. Date: 07/10/2016 (Man. Year: 2016) Chassis No: JTDKB3FU103531172

Colour: Blue Odometer: 813855 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,146.87	16.50	2,130.37	99.23
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		1,640.00	880.00	760.00	46.34
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,797.87	907.50	2,890.37	76.11
	Approved Total (Overridden) (S\$)		750.00		
	(S\$)	3,797.87	750.00	3,047.87	80.25
	+ GST 7.00/7.00% (S\$)	265.85	52.50	213.35	80.25
	Nett Amount (S\$)	4,063.72	802.50	3,261.22	80.25

**INSPECTION** 

Date of Assignment: 14/06/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 15/06/2022 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jul 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHA2331G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	503.04 FL	-	*- FL
2	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	112.70 FL	-	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
4	1		*REAR BUMPER LOWER EXTENSION RH	Repair	232.00 FL	-	*- FL
5	1		*REAR FENDER SHIELD RH	Not Necessary	134.20 FL	-	*- FL
6	1		*REAR WHEEL RIM RH (Not Necessary)	Old Damaged	1,570.55 FL	-	*- FL
7 F=Fra	1 Inchise	part. L=Listli	*REAR WESTLAKE TYRE RH (Not Necessary)	Old Damaged	216.00 F	-	*-F
1 -1 10	111011150	part. L-Listi	emble.	Sub Total (S\$)	2,790.49	22.00	
			- List Item Discount on L Items	25.00/25.00% (S\$)	643.62	5.50	
				Total Parts (S\$)	2,146.87		16.50
			Report was unsubmitted during	this print-out.			]

# Recommended Miscellaneous Items

No Q1	ty Particulars		Repairer's	Amount	
Miscellaneous Items					
1 1	OD/TP Case (Insurer)		11.00	11.00	
		Sub Total (S\$)	11.00	11.00	

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING (REAR FENDER RH ETC)	New	800.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	WHEEL ALIGNMENT	New	120.00	0.00
4	R/I REVERSE SENSORS	New	120.00	30.00
		Gross Labour Cost (S\$)	1,640.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >