



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005683/Ancq2	
			Date: 29/09/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMR 351M	Veh. Inspected	SJC 902M	
Policy No.	D21MTPV01016814	Coverage (\$)	0.00	
Claim No.	CMTD2201961/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	15/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA CX-5	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JM6KE1031E0253543	Colour	GREY	
Odometer	142355 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R19	TOYO	6 mm	
L/H Front Tyre	225/55 R19	TOYO	6 mm	
R/H Rear Tyre	225/55 R19	TOYO	6 mm	
L/H Rear Tyre	225/55 R19	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/06/2022	Inspection Date	16/06/2022	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	