

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/06/2022
TP Veh Reg No: SJE6161J

Estimate No: EST2200176

Date: 08 Jun 2022

Veh Reg No: **SMQ9183C**

Make/Model: TOYOTA VIOS 1.5E
(AUTO)

Chasis No: MR2B23F3401182259

Reg. Date: 10/12/2019

Your Ref No: SJE6161J

Estimate Repair Cost to Vehicle No :SMQ9183C

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Supplementary Parts to Repair		
	List Price		
1	1 PC REAR FENDER MUDFLAP RH	98.60	
		98.60	
	Less 25%	24.65	73.95
	Total		S\$ 73.95
	GST Amount		S\$ 5.18
	Total Amount Payable		<u>S\$ 79.13</u>

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE