

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 16 Aug 2022

Preliminary Advice

Insured Vehicle No	: SCH8182C	Accident Date	: 13/06/2022
TP Vehicle No	: SJU2783G	Assignment Date	: 14/06/2022
Make	: TOYOTA WISH	Est. Duration of Repair	: 4
Date of Inspection	: 14/06/2022		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,812.78
Revised Amount	:S\$	4,739.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,739.68
 Lump Sum Repair	 :S\$	 3,800.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	27,672.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,328.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.