

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : YEO HUN BOON

Vehicle No : SJU2783G

Make/Model : TOYOTA WISH

Accident date : 13.06.2022

26EW

TP MS16
Hi Ray

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Front support panel <i>Repair</i>	1	\$ 1,069.50 <i>x</i>
2	Front bumper <i>Distorted</i>	1	\$ 530.10 <i>✓</i>
3	Front bumper side holder @ \$188.60 <i>2H Bnd</i>	2	\$ 377.20 <i>85</i>
4	Front bumper lower lip <i>Deformed</i>	1	\$ 850.00 <i>✓</i>
5	Front bumper lower LH side grille <i>Neu</i>	1	\$ 216.10 <i>x</i>
6	Front bumper lower centre grille <i>lit</i>	1	\$ 277.00 <i>✓</i>
7	Front grille <i>Neu</i>	1	\$ 525.40 <i>x</i>
8	Front LH headlamp <i>Cracked</i>	1	\$ 1,883.60 <i>1222</i>
9	Front LH headlamp lower panel <i>Neu</i>	1	\$ 189.70 <i>x</i>
10	Front LH fender <i>Deformed</i>	1	\$ 933.60 <i>645</i>
11	Front LH fender inner shield <i>torn</i>	1	\$ 181.70 <i>✓</i>
12	Front LH air duct <i>Cracked</i>	1	\$ 333.70 <i>186</i>
13	Front horn	1	\$ 276.10 <i>✓</i>
			\$ 7,643.70
	Less 25% Disc		\$ 1,910.93
	Total		\$ 5,732.78

Special Nett Items

1	Front bumper clips (1 set) <i>Neu</i>	1	\$ 60.00 <i>30</i>
2	Front grille clips (1 set) <i>Neu</i>	1	\$ 60.00 <i>x</i>
3	Front LH fender inner shield clips (1 set) <i>Neu</i>	1	\$ 60.00 <i>30</i>
	Total		\$ 180.00

Labour Cost

1	To check wiring	1490	\$ 50.00 <i>30</i>
2	Remove & reinstall air con fill in gas		\$ 200.00 <i>x</i>
3	Remove, replace & repair consistent to the accident		\$ 1,200.00 <i>600</i>
4	Respray painting		\$ 1,300.00 <i>800</i>
5	To spray full coat <i>150</i>		\$ 2,750.00
	Total		\$ 2,750.00

Grand Total \$ 8,662.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Total: 4735.60

h/s: 3-8K

04 Days

3-8K