

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

CL(S)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/06/2022
Vehicle Reg. No.:	SHC3242M	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	01/08/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU047993	Chassis No:	KMHC851CVJU103778
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,664.56
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	2,495.56
+ GST 7.00% (\$)	174.69
Nett Amount (\$)	2,670.25

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Jun 2022)

Lim Tien Siong

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3242M/13/06/2022 14:10**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	451.25 FL
3	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	155.00 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	394.80 FL
5	10		*REAR BUMPER CLIPS	20.00	0.00	22.00 FL
6	1		*REAR BUMPER FOGLAMP	20.00	0.00	201.50 FL
7	1		*REAR BUMPER SMARTKEY ANTENNA	20.00	0.00	40.50 FL
8	1		*REAR BUMPER MAT	0.00	0.00	50.00 F
9	1		*REVERSE SENSORS	0.00	0.00	180.00 F
10	1		*REAR NO.PLATE WITH TRIM COVER	0.00	0.00	55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 2,009.45

- List Item Discount on L Items (S\$) 344.89

Total Parts (S\$) 1,664.56

ComfortDelGro Engineering Pte Ltd/SHC3242M/13/06/2022 14:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Lim Tien Siong

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350

400.00

2 SPRAY PAINTING

New

250

300.00

3 R/I REVERSE SENSOR

New

80

120.00

Gross Labour Cost (S\$)

820.00

ComfortDelGro Engineering Pte Ltd/SHC3242M/13/06/2022 14:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphik 97495749
'WP' 15/6/2022 4pm
L/S Kemy after repair
2 days
tanphik@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 13.06.2022 13:40

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4276556

JC NO.305519413

TOMER

AS COMFORT TRANSPORTATION PTE LTD
TOMER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.


REGN NO.: SHC3242M	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 11.06.2022 14:30
YR OF MANU. 01.08.2018	TARGET DATE
CHASSIS CODE KMH851CVJU103778	COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 11.06.2022
ATURE: 3P 11.06.2022

/NO LABOR CODE
00010 PB

DESCRIPTION
PANEL BEATING-SHC3242M-TP



ICKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Jo.: SHC3242M LIMITS

Vehicle No.: SHC3242M

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard